

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 5 - 6 - 7 - 8.

Find BT's. & Set $\frac{3}{4}$ " Iron Pipe & Post from which:
18" Cedar bears S.46°E. 41.5 ft. 24
63
26" Cedar bears N.79°E. 57.3 ft. (Not recorded in Orig. notes)
48" Fir bears S.45°W. 3.3 ft. (now a snag)
30" Fir bears N.30°W. 8.6 ft.
12" Cedar bears N.25°E. 63.3 ft. (Down)

$\frac{1}{4}$ Section Corner to Sections 5 and 8.

Find Mound of Stone & the Stone mkd. $\frac{1}{4}$.
Set New Post in Mound from which:
18" Hemlock bears N.25°E. 26.4 ft. (Gone) 25
122
16" Hemlock S.15°E. 6.9 ft.
New BT: 21" Fir bears N.33°E. 49.7 ft. (Scribed).

Section Corner to Sections 4 - 5 - 8 - 9.

Find Original Stone for Corner in place from which:
18" Hemlock bears N. 25°E. 8.6 ft. 26
123
21" Hemlock bears N.78°W. 29.4 ft. (BT tag on face)
The Hemlock S.40°W. is down. Scribing still visible.

$\frac{1}{4}$ Section Corner to Sections 5 and 6.

Find the Fir marked for the $\frac{1}{4}$ Section Corner from which:
18" Fir bears N.61°E. 5.5 ft. ~~27~~
#32
18" Fir Snag N.34°W. 42.0 ft.

$\frac{1}{4}$ Corner common to Sections 25 and 26.

Corner re-established & new BT's. scribed by Wallace D. Owen #57
on Jan. 5, 1959. ~~Ren. #2~~
The BT's. Mr. Owen scribed have blown over and are to be logged.
I scribed 2 new BT's. as follows:
7" Fir S.79 $\frac{1}{2}$ °E. 32.8 ft. scribed $\frac{1}{4}$ S, R 4186 BT.
6" Fir S.81 $\frac{1}{2}$ °W. 108.4 ft. scribed $\frac{1}{4}$ S R4186 BT. 28

$\frac{1}{4}$ Corner to Sections 28 and 33.

Found - Stone at Corner, checks for, size markings not found.
Also find 40", now 40" Fir Snag, N.18°E. 33.0 ft., shows
good scribing, "BT". S.E. BT. not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S28 T31S
Office, 1963 S33 R9W
New BT's: 6" Laurel bears N.65°W. 37.9 ft. scribed $\frac{1}{4}$ S28 CS BT.
20" R. Fir bears South 61.0 ft. scribed $\frac{1}{4}$ S33 CS BT. 29
May 28, 1963

$\frac{1}{4}$ Section Corner to Sections 2 and 1.

Found - Both BT's., alive & standing & very old Yew Post, rotted.
8", now 16" Fir S.45°W. 30.4 ft., open & shows " $\frac{1}{4}$ ".
6", now 8" Chinq. S.45°E. 28.4 ft., recorded as S.50°E.
Shows good scar.
Set - Brass Cap at Intersection of slope distances & #157
bearing to Fir BT, Mkd: County Surveyor's Office, 1964
T31S R9W $\frac{1}{4}$ S 2/S 1
New BT's: 7" Hemlock N.69°E. 20.4 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
8" Hemlock S.78°W. 29.9 ft. Mkd: $\frac{1}{4}$ S2 CS BT.
Note - This corner lies approx. 75.0 ft. south of Dry Creek.
bottom on steep, north slope.
Renewed by Vernon R. Tracy & Crew, Oct. 1964. C.S. File 53/25 30

Clifford A. Stephens
Surveyed For: Coos Head Timber Co.
Date: Dec. 1959 - Feb. 1961
C. S. File No. 51/178
Map File M 20 - 16.

Robert Dollar C
By L.V.
Swearingen
May 1963
C.S. File
No. 51/68

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
Begun May 28, 1963
C. S. File No. 53/25