

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

39

Sec. Cor. to Secs. 4 & 5, T31-9W. & Secs. 32 & 33, T30-9W.
Found - 10", now 13" D.Fir N. 50° E. 6.6 ft. (should be 10.4 ft.)
shows good scar.
33" D.Fir, now 40", S. 39½° W. 50.8 ft. (should be 48.8 ft.)
shows fair scar.
11", now 15" D.Fir S. 85¾° W. 24.4 ft., shows good scar.
12" Fir, down, N. 85° W. 39.6 ft., opened for scribe "BT".
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1965

T30S R9W	
S 32	S 33
S 5	S 4

T31S

New BT's: 34" D.Fir N. 71° W. 42.5 ft. scribed T30S R9W S32 CS BT.
Could not match distances, so took 4 bearings and 2 distances.

40

¼ Corner to Sec. 4, T31-9W. & Sec. 33, T30-9W.
Found - 20 x 12 x 10" Stone with ¼ on N. Face.
36" Fir N. 2½° W. 14.5 ft. This tree blown down on face.
Shows two good faces.
10" Hemlock, Now 21" S. 79½° E. 12.2 ft., tree shows scar.
(Did not open tree as it was getting late. Call very good on stream.)
Set - Brass Cap at ¼ Cor.Mkd: County Surveyor's Office, 1965

T30S	
¼ S 33	R9W
S 4	

T 31S

New BT's: 21" Hemlock S. 79° E. 12.5 ft. scribed ¼ S4 CS BT.
56" Cedar N. 38° E. 21.6 ft. scribed ¼ S33 CS BT.

John M. Powell
F. Jones & J. Brady
November 1965
C. S. File No. 53/53

41

Wit. Cor. To Sec. 6, T31-9W. & Sec. 1, T31-10W.
Found - 60" Fir Stump S. 32° E. 17.8 ft., opened for scribing,
found "BT".
30" Fir Snag N. 63° W. 37.0 ft., found to be 32.0 ft.,
Did not find any scribing on this snag. T31S
Set - Brass Cap at W.C.Mkd: County Surveyor's Office, 1965

W.C. to	
R10W	S 1 S 6
	R9W

New BT's: 14" Chinq. S. 42° W. 47.6 ft. scribed T31S R9W S1 CS BT.
7" Laurel S. 26° E. 65.6 ft. scribed T31S R10W S6 CS BT.
This corner is located right on top of ridge next to steep bluffs.

42

South ¼ Corner of Section 34 only.
Re-established by L.V. Swearingen, Nov. 1963. (See Ren. # 9)
Of the two bearing trees established, the
12" Incense Cedar N. 15° E. 92.2 ft. is in good condition
8" Fir S. 32½° E. 24.9 ft. was destroyed in a clear cut
logging operation.
New BT: 10" Fir S. 17½° W. 88.0 ft. scribed ¼ S RE 3642 BT.
(Although this tree is agin in Sec. 3, T32S R9W,
I felt it best suited the purpose)

Nov. 18, 1965

Milner L. Larson
For Robert Dolllar Co.
Nov. 18, 1965
C. S. File # 51/68

43

¼ Corner to Sections 23 and 24.
Found - 20" Doug. Fir BT. S. 60° E. 16.5 ft., good condition.
14" Doug. Fir BT. - S. 60° W. 7.9 ft., destroyed in
clear cut operation.
For the corner, I set a 1½" x 30" Iron Pipe, 28" in the ground.
Referenced for Sec. 23 - 10" Doug. Fir, N. 4° W. 15.3 ft., scribed
"¼ S RS 749 BT".
Bearing Tree was referenced with staff compass & chain, Mag.Var. 19½° E.

T. H. Mehl, III
For Robert Dolllar Co.
Oct. 12, 1966
C. S. File No. 55/15