

Douglas County Surveyor's Record of
Government Corners Renewed

T. 31 S. T. S. R. 9 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

140

Sec. Cor. to Secs. 7 & 18, R9W. & Secs. 12 & 13, R10W.
Found - Corner Tree, now stump, shows good scars.
50" D. Fir, now stump, N. 42° E. 35.6 ft., shows good scars.
40" D. Fir, now Stump, S. 60° E. 34.3 ft., shows good scars.
10" D. Fir, now 14" Stump, S. 50° W. 43.6 ft., opened for scribe, "BT".
36" D. Fir, now 38" Stump, N. 55° W. 20.5 ft, shows good scars.
Set - Brass Cap on N. side of Corner Tree Stump. R T 31 S R
(B.C. lies 4.0 ft. County Surveyor's 10 S 12 S 7 9
N. of center of Stmp) Office, 1967 W S 13 S 18 W
New BT's: 12" Chinquapin S. 22° E. 133.2 ft., mkd. T31S R9W S18 CS BT.
14" Hemlock S. 12° W. 146.7 ft. mkd. T31S R9W S13 CS BT.
Location Tag on 36" Fir Stump S. 41° W. 60.7 ft. on skid trail

141

1/4 Corner to Section 17 and 16.
Found - No trace of Iron Pipe, this area being heavily logged, Ren. #14.
36" D. Fir, now 36" Stump, N. 76° E. 18.3 ft., badly burnt face,
no good scribe left, faint "BT".
12", Now 14" D. Fir N. 5° E. 27.3 ft., scribe visible "BT 1/4".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 31 S R 9 W
Office, 1967 1/4 S 17 S 16
New BT: 13" Hemlock S. 54° W. 73.8 ft. mkd. 1/4 S17 CS BT.

142

1/4 Corner to Sections 5 and 6.
Found - I. Pipe at 1/4 Corner, See Ren. #32.
18" Fir, now 20" Stump, N. 32° W. 41.5 ft., shows good scar.
22" D. Fir, now stump, S. 27° E. 57.4 ft., scribe visible, 1/4 S5 BT.
Set - Brass Cap alongside I. Pipe mkd: County Surveyor's T 31 S R 9 W
Office, 1967 1/4 S 6 S 5
New BT's: 8" Hemlock S. 78° W. 50.5 ft. mkd. 1/4 S6 CS BT.
10" Cedar N. 7° W. 57.3 ft. mkd. 1/4 S 6 CS BT.
No trees in Section 5.

143

1/4 Corner to Sections 30 and 31.
Found - 18" Corner Tree, now 18" Snag, scribe visible, "1/4 S30" on N. Face,
South face rotted.
36" D. Fir N. 5° E. 23.2 ft., old face badly burnt (Rec. 19.8 ft.)
found scribe marks, not legible.
14", now 20" D. Fir, S. 60° E. 7.9 ft., shows good scar.
Set - Brass Cap on S. side of Corner Tree Mkd: T 31 S R 9 W
County Surveyor's 1/4 S 30
Office, 1967 S 31
New BT: 9" Laurel N. 70° W. 12.0 ft. mkd. 1/4 S30 CS BT.

144

Sec. Corner to Sections 31 and 32 only, T31-9W.
Found - Brass Cap at Sec. Cor., properly mkd: GLO 1917
8", now 9" Yew, N. 31° W. 32.6 ft. (Rec. 31*) faint scribe visible "TS"
8", now 8" Yew, N. 16° E. 26.5 ft. (Rec. 25.1') all scribing rotted off
New BT's: 21" D. Fir N. 83° W. 42.5 ft. mkd. T31S R9W S31 CS BT.
38" D. Fir N. 80° E. 42.0 ft. mkd. T31S R9W S32 CS BT.
Note - This cor. lies on steep, N. slope approx. 80' S. of small creek
and 660.0' W. of Slide Creek.

145

1/4 Corner to Section 32 only, T31-9W.
Found - GLO Brass Cap properly marked in 1917.
Orig. 38" D. Fir S. 78° E. (48° face) shows good scars.
18" D. Fir, now 29" Stump, N. 27° E. 109.6 ft., opened for scribe, "3".
Tree recently logged, opened Log.
New BT's: 12" Pine N. 12° W. 22.4 ft. mkd. 1/4 S32 CS BT.
13" Pine N. 52° E. 69.3 ft. mkd. 1/4 S32 CS BT.
Note - This corner lies on top ridge, running approx. N. 20° E. - S 20° W.

John M. Powell
Frank Jones & J. Brady
May, 1967
C. S. File No. 54/32