

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 31 S. T. S. R. 9 W. R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97101

162

Center 1/4 Corner to Sec. 6 See Ren. #31.  
Fd. - 4" square post established by C.S. Lehmanowsky in 1956. See  
Ren. #31.  
46" Fir BT bears N.36°W., 74.1 ft. is now a stump with plain  
scribes.  
36" Fir BT bears S.71°E., 59.6 ft. is now a stump with plain  
scribes.  
Set - 5/8" Rod by the squared stake at the corner.  
New BT's - 10" Hemlock bears N.22°30'E., 18.3 ft. and scribed "C1/4 S 6  
B.T. 378".  
10" Hemlock bears S.14°00W., 21.7 ft. scribed "C1/4 S 6 B.T.".

Jack E. LaFlamme  
RI #378  
F Georgia Pacific  
N 1980  
C. 58/248

Greg Quibell  
D. Stewart  
Doug. Co. Surveyors  
Office  
Feb. 19, 1981  
C.S. 61/19

163

1/4 Corner for Sec. 12; and Sec. 7 of T.31-8  
Found - 1962 BLM brass cap in good condition buried in the ground  
approx. 8", properly stamped.  
Stump of orig. 42" now 47" Fir BT with BLM BT tag bears West  
13.2 ft. to the face.  
Stump of orig. 48" Fir BT (Sec. 7) which has rolled over and slid  
down hill almost on top of the cap.  
Set - Boat spike in top of orig. Sec. 12 BT stump which is now 47"  
Spike bears West 14.5 ft.  
Boat spike in top of 48" Fir stump which bears N.38°E., 66.9 ft.  
Both stumps have new BT tags. No tree suitable for scribing are in the  
vicinity.

2/19/81

164

Section corner for Secs. 6 and 5; and 31 & 32 of T.30-9  
Found - A 1965 County brass cap properly marked on a 1" I.P. firmly set  
protrudes 18 1/2" above ground. Ren. #38  
a 1 1/4" I.P. protrudes 18" from the ground on the south edge of  
brass cap. Ren. #33  
A 14"x10"x8" stone is set on the west side of the brass cap. Stone  
is mkd. with 5 notches on its east edge, no marks fd. on the  
west edge. (broken) (Rec. 5 notches on east, 1 notch on west)  
1893 retracement.  
An iron fence post protrudes 42" from ground on the southwest edge  
of the brass cap.  
A search is made for the orig. bearing trees. None are found.  
Found - 1893 BT, a Fir, 30" now a 30" DBH 50 ft. tall D. Fir snag, bears  
N.44°E., 42.9 ft. Tree has good evidence of burling around a  
rotted & burned blaze. No scribing visible.  
1893 BT, a Fir snag, 30 ft. tall & 30" DBH bears S.22 1/2°E.,  
43.2 ft. face measurement. No scribing or definite blaze marks  
are found but this tree agrees reasonable well with 1893 Fir,  
30" bearing S.22°E., 42.9 ft.  
1893 Fir, 34" now a rotted 30", 12" tall burned fir stump bears  
S.21 1/2°W., 32.3 ft. No blazes or scribe marks visible.  
Northwest bearing tree, 1893, is searched for but not found.  
Found - An 8" D. Fir, now a 12" DBH D. Fir bears S.60°W., 4.4 ft.  
Tree has a well healed single blaze. No scribing visible. #33  
A 10" Oak now a 12" DBH Chinquapin bears S.51°E., 20.4 ft. Tree  
has a partially healed single blaze with the scribing S5 BT  
visible. Ren. #33

Found monument position is accepted.  
No other suitable bearing trees are available.  
All found trees are tagged with DCSO bearing tree tags.

4/7/81

165

1/4 Corner for Section 5; and Sec. 32 of T.30-9  
Found - 1967 County brass cap, properly mkd., on a 1" I.P. firmly set &  
protruding 6" from ground. Ren. # 148  
1893 resurvey, a stone measuring 14"x10"x4" is deposited on top  
of ground & set on the east side of the B.C. Stone is marked 1/4  
on its top side. (rec. 1/4 on N. face)  
A steel fence post protrudes 36" from the ground on the west side  
of the B.C. monument.  
Possible remains of orig. southeast 18" fir are found near record bearing &  
distance. No evidence of the other orig. bearing tree is found.  
Found - 1893, a Fir 18" is now a burned D. fir snag 18" DBH. approx. 35 ft.  
tall bears S.34°E., 17.5 ft. to face measurement (rec. S.33 3/4°E  
17.5 ft.) Tree has good evidence of burned blazes. No

Stephen J. Flause, Deputy  
Douglas County Surveyors Office  
Witnesses: K. Mosely; T. Plouff  
April 7, 1981  
C.S. 61/19