

Douglas County Surveyor's Record of
Government Corners Renewed

T 31

T. S.

R 9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

173

Section Corner for Secs. 28, 29, 32 and 33

Found - 1967 2½" dia. DCSO brass cap on a 1¼" O.D. iron pipe protruding 7" above ground. Ren. #108
24" now 28" dia. tipped out and laying on blaze. D. Fir bears S.10°W., 13.9 ft. to root hole (agrees with rec.) Orig. B
10" now 11" dia. live Oak with scribing visible on an unhealed double blaze "T31S R9 S11 CS BT" bears S.65°E., 32.7 ft. (Rec. S.65°E., 35.0 ft. distance is a slope measurement. g.
No other original BTs found.
36" now 36" dia. 8 ft. high D. fir snag with scribing visible on an unhealed single blaze, "T31S R9W S29 CS BT" bears N.4°W., 40.4 ft. (agrees with rec.) Ren. No. 108
26" now 31" dia. standing dead D. fir with scribing visible on an unhealed double blaze "T31S R9W S28 CS BT" bears N.76°E., 30.0 ft. (agrees with BT tag, Renewal records is N.75°W., 30.0 ft.) Ren. No. 108.
New BTs - 28" dia. D. fir double blazed and scribed "T31S R9W S33 CS BT" bears S.26¼°E., 39.3 ft.
17" dia. D. fir double blazed and scribed "T31S R9W S33 CS BT" bears S.2¼°E., 60.3 ft.
3" dia. pistol butt D. fir double blazed and scribed "X BT" bears N.33½°W., 65.8 ft. to center of trunk at upper blaze height (center of root crown difficult to determine.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
April 3, 1990
C.S. 64/6

4/3/90

Section Corner for Secs. 5 & 6 in T31 R9; and 31 & 32 in T30 R9

Found - 2½" dia. DCSO brass cap on 1½" o.d. I.P. protruding 18" above ground. (Ren. No. 38). See Ren. No. 164. 174
14"x10"x8" w/5 notches on east edge found on top of ground along west edge of DCSO BC/IP. (1893 Retracement Survey)
1½" i.d. I.P. protruding 18" above ground found along SE edge of DCSO BC/IP. (Ren. No. 33)
Metal fence post along south edge of BC/IP
30" now 37" dia. 30 ft. high D. Fir snag w/previously opened blazes, no scribing visible, bears S.22°E., 44.5 ft. (Rec. S.22°E., 43.2 ft., distance is a face measurement) 1893 BT
34" now decayed fir stump, no blazes or scribing visible bears S.21½°W., 32.3 ft. (agrees with Rec.) 1893 BT
30" now 30" dia. 3 ft. high D. Fir stump with fully healed blaze, bears N.44°E., 42.9 ft. (agrees w/Rec.). 1893 BT
8" now 14" dia. D. Fir w/fully healed blaze, bears S.60°W., 34.4 ft. (agrees w/Rec.). Ren. No. 33.
10" Oak now 15" dia. Chinquapin w/small healed blaze 5 ft. above ground and a rotted out center, bears S.51°E., 20.4 ft. (agrees w/Rec.). Ren. No. 33
New BTs - 6" dia. Chinquapin double blazed & scribed "T31S R9W S5 CS BT" bears S.30°E., 15.4 ft.
5" dia. Chinquapin double blazed & scribed "X BT" bears N.42°E., 19.8 ft.

Douglas County
Surveyors Office
Randall Smith
Ed Monrean
Sept. 21, 1992
C.S. 64/32

9/21/92

175

Section Corner for Secs. 16, 17, 20 and 21. CORNER REPORT ONLY

Found - Possible original stone measuring approx. 18" x 12" x 8" (as per record) lies on north edge of 2½" dia. brass cap from Renewal # 118 & Ren. # 169. Brass cap is on a 1 3/8" I.P. firmly set & protruding approx. 1 ft. above a 2 ft. d mound of stone. (Notches not apparent on fd. stone; did not disturb stone mound to examine entire fd. stone.)

Evidence of 2 original BTs fd.; NE & NW orig. BTs gone.
A fir 30" dia. now a 25' tall 40" dia. breast high fir snag w/scribing "T31S R9 S21" visible on an open blaze bears S.38°E., 86.4 ft. (Original record S.38°E. 84.5 ft., possibly a face measurement.)
A fir 36" dia. now a 45" dia. breast high Douglas Fir w/fully healed blaze & various cruisers marks bears S.45°W., 68.2 ft. (Original rec. S.45°W., 66.0 ft.; possibly a face meas.)
Found 4 bearing trees from Renewal # 118:
8" D. Fir now 14" D.B.H. w/fully healed double blaze bears N.26°E., 18.6 ft. (as per record).

Douglas County
Surveyors Office
Stephen Flause
John Pike
Oct. 8, 1992
C.S. 64/32