

Douglas County Surveyor's Record of  
Government Corners Renewed

32 T. S. 1 R. W. W. M.

To establish North One-Quarter ( $\frac{1}{4}$ ) corner, Section 5, Township 32 South,  
Range 1 West, Willamette Meridian, Douglas County, Oregon.

Location: North boundary Township 32 South, Range 1 West, #19  
Willamette Meridian, Douglas County, Oregon.

Found corner monuments as shown on map. Set  $\frac{3}{4}$ " G.I. pipe for  
Quarter Sec. corner monument of Section 5, in accordance with  
procedure prescribed by law.

North section corner between secs. 5 and 6.  
Found - Ground of stone and stake - Stone chiseled.  
Blazed and scribed two trees.

14" white fir - S 61° W., 93.2 ft. mkd. T 32 S, S 6 CS B.T.

10" red fir - S 16° E, 115.0 ft. mkd T 32 S, S 5 C.S. B.T.

No other trees available.

$\frac{1}{4}$  Section Corner to Sections 4 & 9.

As determined by O. B.T.

32" Fir bears N.25°W. 11.9 ft. dist., O.B.T., fd. scribe. #73

At Corner Point set  $1\frac{1}{2}$ " x 30" Iron Pipe from which

12" Fir bears N.4°E. 35.2 ft. dist. mkd.  $\frac{1}{4}$  S 24 B.T.

7" Maple bears S.40°W. 26.5 ft. dist. mkd.  $\frac{1}{4}$  S 9 B.T.

50" Fir bears S.26°E. 33.5 ft. dist., bark scribed  $\frac{1}{4}$  S 9 B.T.

Corner lies just West of Rock Bluff.

Sec. Cor. 3, 4, 9, 10, bears S.80°10'E. approx. 2900.0 ft.

Closing Corner to Sections 6 and 5.

I find corner as renewed by County Surveyor, 1952, Ren #1  
A Stone Mound, 14" W. Fir B.T. S.61°W, 93.2ft. (actual 91.6ft.)  
now dead.

I scribe New BT's: 8" Maple S.1°40'W. 106.9 ft. #17  
5" W.Oak North 55.6 ft.

No other live trees available.

Corner to Sections 31 and 32 only, T31-1W - North Bdry. T32-1W. #10

Found - Brass Cap at Corner & Orig. Bearing Trees: #54

Orig. 40", now 44" Cedar N.1°W., not N.5°W. 13.2 ft., shows scars.

Orig. N.38°E. 44.2 ft. Cedar BT., now down, shows scribing.

New BT's: Rescribe Orig., now 48" Cedar N.1°W. 15.5 ft. scribed S31  
T31S RLW CS BT.

16" W. Fir bears N.38°E. 54.5 ft. scribed S32 T31S RLW CS BT.

$\frac{1}{4}$  Corner to Sections 7 and 18. #11

Found - Orig. 34", now 40" Cedar Snag S.10°W. 9.9 ft., shows good #12  
scribing, previously opened, "S".

Orig. N. E. BT. not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S 7 T32S RLW  
Office, 1963 S18

New BT's: 30" Cedar bears S. 3° E. 17.5 ft. scribed  $\frac{1}{4}$  S18 CS BT.

12" W. Fir bears N.74°W. 51.2 ft. scribed  $\frac{1}{4}$  S 7 CS BT.

$\frac{1}{4}$  Corner to Sections 6 and 7. #12

Found - Orig. 12", now 16" Dead Fir S.50°W. 6.6 ft., shows good  
scribing "S". Orig. N.E. BT. not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S 6 T32S RLW #25  
Office, 1963 S7

New BT's: 14" W. Fir bears N.60°W. 17.2 ft. scribed  $\frac{1}{4}$  S6 CS BT.

22" R. Fir bears S.72°W. 12.0 ft. scribed  $\frac{1}{4}$  S7 CS BT.

6  
Completed Mar 18, 1953  
Leland P. Lovejoy  
Registered Land Surveyor  
For: Mr. L. E. Gilliam  
Ashland, Oregon  
Map in Surveyor file  
41/159  
County Surveyors  
Office - Jim  
Byron and Ray  
Irving.  
July 27, 1953  
Filed Drawer 45,  
Env. 176

John H. Markham, Jr.  
Wit: C.G. Meade  
For Stomar Lbr. Co.  
April 28, 1959  
C.S. File No.  
51/17

9  
R. M.  
Thompson  
For John Toumey  
Feb. 8, 1960  
C. S. File  
No. 51/171

10  
James W. Byron, Deputy County Surveyor  
Mike Darby and Wm. Stoffel  
March 1963  
C. S. File No. 53/15

RE-RENEWED, SEE CORNER NO. #25