

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 1 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

31

$\frac{1}{4}$ Corner to Sections 16 and 17.
Found - 6" Fir, now 14" Windfall, N.75°E. 6.6 ft. This tree has been rescribed: " $\frac{1}{4}$ S BT".
10" Fir, now 22" Stob, S.34°W. 2.6 ft. This tree has been rescribed: " $\frac{1}{4}$ S17 BT". Also found Orig. scribings of "BT" #55 in about 10 inches.
Set - Brass Cap at Cor. MKd: County Surveyor's Office, 1968 T 32 S R 1 W
 $\frac{1}{4}$ S 17 | S 16
New BT's: 14" R. Fir N.89°E. 65.1 ft. mkd. $\frac{1}{4}$ S 16 CS BT.
12" R. Fir S.45°W. 26.8 ft. mkd. $\frac{1}{4}$ S17 CS BT.
This $\frac{1}{4}$ Corner lies on E. edge of a N - S. cutting line & 165 ft. south of a spring branch. 7/31/68

32

Section Corner to Sections 4 - 5 - 8 - 9.
Found - 40, now 40" D. Fir, S.49°W. 17.8 ft., scribe visible.
7", now 9" Cedar, N.63°W. 9.2 ft., shows good scar.
12" Fir, now down, S.45°E. 26.4 ft.
20", now 20" D. Fir, N.61°E. 24.6 ft. (Rec. N58E 22.4), shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 32 S R 1 W
S 5 | S 4
S 8 | S 9
New BT: 12" Cedar S. 18° E. 14.8 ft. mkd. T32S RLW S 9 CS BT.
All other Bearing Trees O.K. and Tagged.

33

$\frac{1}{4}$ Corner to Sections 5 and 4.
Found - Stone at corner, approx. size, but no marks.
22", now 24" D. Fir, N.68°W. 17.8 ft., shows good scar.
20", now 22" D. Fir, S.56°E. 15.8 ft., prev. opened, scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 32 S R 1 W
 $\frac{1}{4}$ S 5 | S 4
Note - All Bearing Trees O. K. and Tagged.

34

$\frac{1}{4}$ Corner to Sections 8 and 9.
Found - Corner Stone mkd: " $\frac{1}{4}$ ".
12", D. Fir, now 11' Snag, N.50°E. 2.6 ft., showed scribe "BT".
Opened the upper face & found " $\frac{1}{4}$ S". Tried to get a ring count but rings are too small. Estimate to be right age.
26" Fir, now a low stump, West 4.6 ft., shows no face.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 32 S R 1 W
 $\frac{1}{4}$ S 8 | S 9
New BT's: 12" D. Fir S. 54°W. 35.1 ft. mkd: " $\frac{1}{4}$ S9 CS BT".
26" D. Fir N. 82° E. 35.5 ft. mkd: " $\frac{1}{4}$ S8 CS BT".
Note - This corner lies along a N - S. cutting line.

35

$\frac{1}{4}$ Corner to Sections 11 and 14.
Found - Orig. 20", now 30" D. Fir, N.45°W. 4.6 ft., shows good scars.
Orig. 14" D. Fir, now stob, S. 5° W. 16.1 ft. (Rec. 13.1) opened for scribe " $\frac{1}{4}$ S".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968 T 32 S R 1 W
 $\frac{1}{4}$ S 11 | S 14
New BT: 15" D. Fir S. 59° W. 18.3 ft. mkd. " $\frac{1}{4}$ S14 CS BT".

36

$\frac{1}{4}$ Corner to Sections 14 and 15.
Found - GLO Brass Cap, firmly in ground, properly marked in 1955.
30", now 32" D. Fir S. 28° E. (Rec. S44E) 18.8 ft., scribe marks visible.
12", now 16" W. Fir, S. 25° W. (Rec. S47W) 64.2 ft., axed face not scribed.
This corner set by proportion, as the types of trees were correct, dist. good and brass cap firmly in ground, I put in new Bearing Tree:
Found no evidence of trees at said bearings.
New BT: 13" D. Fir S. 40° W. 67.5 ft. mkd: " $\frac{1}{4}$ S15 CS BT".

John M Powell
Frank Jones & W. Penley
July & August, 1968
C. S. File No. 54/71

RE-RENEWED, SEE CORNER NO. #55

RE-RENEWED, SEE CORNER NO. #102

RE-RENEWED, SEE CORNER NO. #109

RE-RENEWED, SEE CORNER NO. #107