

Douglas County Surveyor's Record of  
Government Corners Renewed

T32 \_\_\_\_\_ T. S. \_\_\_\_\_ R1 \_\_\_\_\_ R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

115

1/4 Cor. Secs. 1 & 2  
Set - 2 1/2" x 30" aluminum pipe with aluminum cap stamped:  
T32S R1W WM  
1/4  
S2 | S1  
RESET 1993  
1980  
PLS 1035

New References -

Doug. Fir, 9" dia., bears N.60°W., 12.7', scribed "1/4 S2 BT"  
Doug. Fir, 7" dia., bears N.18°W., 10.7', scribed "1/4 S2 BT"  
Hemlock, 15" dia., bears S.82°E., 23.8', scribed "1/4 S1 BT"  
Doug. Fir, 7" dia., bears S.8°W., 8.8', scribed "1/4 S1 BT"  
A 5/8" x 30" iron rod with yellow plastic cap stamped "NYGREN  
LS 1035", bears N.0°20'55"W., 234.74'. (Previous location  
of 1/4 cor.) (REN # 86)

116

Cor. Secs. 2, 3, 10, & 11  
Found - 2 1/2" iron pipe (bent) with brass cap stamped: (REN # 103)  
U.S. GENERAL LAND OFFICE SURVEY  
T32S R1W  
S3 | S2  
S10 | S11  
1955

NOTE: Iron pipe is bent Northerly, the following bearings & distances  
were measured from that portion of pipe which is vertical &  
below bend.

Found - Douglas Fir snag, 48" dia., bears N.70°E., 34.8', healed  
blaze.  
Douglas Fir stump, 63" dia., bears S.75°W., 11.2', healed  
blaze.  
Douglas Fir, 36" dia., bears S.89°E., 67.0', healed blaze.  
Douglas Fir, 30" dia., bears N.65°W., 82.5', healed blaze.  
Douglas Fir, 46" dia., bears N.50°W., 22.6', healed blaze.  
Douglas Fir, 10" dia., bears S.46°W., 6.0', visible scribe.  
New BT- Douglas Fir, 6" dia., bears N.6°E., 8.9', scribed "T32S R1W  
S2 BT"

117

1/4 Cor. secs 2 & 11  
Found - 2" x 32" galvanized iron pipe with a 2 1/2" dia., brass cap  
stamped:

T32S R1W

1/4 S 2  
S11

C.S. 1981

Douglas Fir, 11" dia., bears S.28°W., 17.0', visible scribe.  
Hemlock, 15" dia., bears N.64°W., 21.1', visible scribe.

New References -

Hemlock, 11" dia., bears S.77°W. 18.4', scribed "1/4 S11 BT"  
Doug. Fir, 9" dia., bears N.80°E., 23.2', scribed "1/4 S2 BT"  
5/8" x 30" iron rod with yellow plastic cap mkd: "NYGREN LS  
1035", bears ~~S.85°17'20"E., 47.66'~~ (Previous location of  
1/4 cor.) (REN #99) S.86°26'27"E (1/13/94 JC DC-SO.)  
48.75 1/10/94

Cor. Secs. 16, 17, 20 & 21  
Found - Iron pipe brass cap & National Forest post/sign. 118  
10" Fir snag N.19°E., 9.9 (15' tall) healed face  
8" Cedar snag N.79°W. 38.4 (8' tall) scribe vis.  
15" Fir rootwad S.72°W., 44.0  
6" Fir S.53°E. 30.9 gone in clear cut.  
New - 15" S.30°E., 10.7 scribed "S21 BT"  
13" Fir N.69°E., 19.6 scribed "S16 BT" #127  
6" Fir N.10°W., 20.1 scribed "S17 BT"  
2 1/2" fir S.16°W., no scribe - tag only.

Gerald Nygren, PLS # 1035  
For: United States Department of Agriculture  
Umpqua National Forest  
July, 1991 thru Sept. 1993  
M 118-20 thru C.S. File 63/134 (N)

Mark Smalley  
For: Roseburg  
Forest Products  
10/4/2002  
C.S. 65/44-19

RE-REVIEWED, SEE CORNER NO. #127