

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 2 W. R. W. W. M.

For: Ump. Nat'l. Forest
By: Glenn S. Baughman
July, 1969
Map File M 38 - 37

Vernon "Ray" Tracy
Vincent Perron
C. S. File No. 54/117

$\frac{1}{4}$ Corner to Sections 20 and 29. 46
Set by proportionate measurement.
Set - 2" x 30" I. Pipe & Brass Cap Stmpd: $\frac{1}{4}$ S20/S29
1969 CS
Scribed: 9" D. Fir bears S. 3° E. 13.7 ft.
8" D. Fir bears N. 26° W. 19.4 ft.

Center $\frac{1}{4}$ Corner to Section 20. 47
Set - 2"x30" Galv. I. Pipe & Brass Cap & Stamped: $\frac{1}{4}$ Sec. 20, 1969
O.L.S. 536
Scribed: 55" D. Fir bears N. 84° 30' E. 204.6 ft.
33" Hemlock bears S. 25° W. 271.3 ft.
July, 1969

Section Corner to Sections 14 - 15 - 22 - 23. 48
Found - Orig. Corner Stone 28x15x8", 3 notches on S. & 2 notches
on E., had been slightly disturbed.
Orig. 12" Fir Snag N. 19 $\frac{1}{2}$ ° W. 13.2 ft., scribing visible.
Orig. 19" Fir Stump N. 83° E. 19.1 ft., good outer face, rotten inside.
No trace of S. E. nor S. W. Bearing Trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 2 W
Office S 15 | S 14
1970 S 22 | S 23
New BT's: 16" Hemlock N. 49° E. 8.3 ft. scribed "T32S R2W S14 CS BT".
10" Hemlock S. 49 $\frac{1}{2}$ ° E. 51.8 ft. scbd: "T32S R2W S23 CS BT".
12" Cedar N. 3° E. 40.7 ft. mkd: "T32S R2W S14 CS BT".
No tree in S. W. limits.
6/15/70

$\frac{1}{4}$ Corner to Sections 15 and 22. 49
Found - Corner Stone, as called for, in place, mkd: " $\frac{1}{4}$ " on N. face.
Orig. 60" Fir, now 64" Fir Stump, S. 29° E. 37.0 ft., shows good axe scar.
Orig. 44", now 48" Fir, turned out, N. 23° W. 39.6 ft., scribe visible on
previously opened Blaze.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 2 W
(Reset Stone alongside) Office $\frac{1}{4}$ S 15
1970 S 22
New BT's: 12" R. Fir N. 27° E. 33.9 ft. mkd: " $\frac{1}{4}$ S15 CS BT".
14" R. Fir S. 69° E. 70.2 ft. mkd: " $\frac{1}{4}$ S22 CS BT".
This corner lies on moderate northerly slope in old logged unit.
7/23/70

$\frac{1}{4}$ Corner to Sections 15 and 16. 50
Found - Corner Stone mkd: " $\frac{1}{4}$ " on W. face, in place, as called for.
Orig. 12", now 18" Fir, alive, N. 80° E. 15.8 ft., scribe visible on
previously opened blaze. We tag.
Orig. 40", now 44" S. Pine, alive, S. 70° W. 9.2 ft., we open & find "S16 BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 2 W
(Reset Old Stone Alongside) Office, 1970 $\frac{1}{4}$ S 16 | S 15
New BT's: 14" Hemlock S. 44° W. 26.0 ft. mkd: " $\frac{1}{4}$ S16 CS BT".
9" D. Fir S. 41° E. 19.0 ft. mkd: " $\frac{1}{4}$ S15 CS BT".
This corner lies on W. side of spur ridge at S. end of Talus area and
large rock outcrop about 20 ft. high, & 30 ft. across.
Found - Line Tree 600 ft. to N. of $\frac{1}{4}$ Corner.
8/3/70

Section Corner to Sections 9 - 10 - 15 - 16. 51
Found - No trace of Corner Stone.
Orig. 14", now 18" Fir, alive, N. 64° W. 16.5 ft. (Rec. N64E). We open
& find scribe "2W".
Orig. 24" Fir, now 26" Stump, S. 46° E. 16.5 ft., scribe visible on log
lying below stump.
Orig. S.W. BT., down, and Orig. N.E. BT., gone.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 2 W
Office S 9 | S 10
1970 S 16 | S 15
New BT's: 14" W. Fir N. 43° W. 25.0 ft. mkd: "T32S R2W S 9 CS BT".
14" D. Fir S. 57° W. 10.1 ft. mkd: T32S R2W S16 CS BT".
14" W. Fir N21° E. 5.1 ft. mkd: "T32S R2W S10 CS BT".
10" W. Fir S. 10° E. 24.4 ft. mkd: "T32S R2W S15 CS BT. scribed
This cor. lies on steep S.W. slope in logged unit. 8/3/70