

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 3 R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 97198

Section corner to secs. 4, 5, 8 & 9. 26
Found 32" Fir, S.70°E., 23.8 feet, marks almost gone, rescribe.
Drive $\frac{3}{4}$ inch I. pipe. Found $\frac{1}{2}$ inch iron pipe N.72°E., 26.2 feet from above
tree but as measurement does not fit notes do not use. Other B. T.s
are gone and no sign of same. Ren. #11
Scribe:
24" Fir, N.58°15'W., 53.8 feet.
20" Fir, S.41°W., 69.2 feet.
No tree in Sec. 4 close enough.

George J. Wenderoth,
Deputy County Sur.
October, 1955.
C. S. File No. 47/17.
MAP M 41-10

Center $\frac{1}{4}$ corner to section 4. 27
Set at intersection of N-S and E-W mid-section lines.
At point for corner - a $\frac{3}{4}$ inch iron pipe,
from which:
An 18" W. Fir, N.24°50'E., 28.0 feet.
A 30" Alder, S.36°12'E., 29.2 feet.

$\frac{1}{4}$ Section Corner Section 6, T32S, and Section 31, T31S 28
Found 1 1/2" I.P. at E-W Fence Line. The N.W. BT. good condition, checks
for bearing & dist. Scribing visible.
The S.W. BT. down.
I blaze & scribe 10" Hemlock S.22 1/2°W. 24.3 ft. S6 T32S R3W $\frac{1}{4}$ Cor. CS BT.

$\frac{1}{4}$ Section Corner to Section 5 & 6. *FD. OR L. HERSTEIN 7-16-81 C.S. 61/27* 29
Found - Both Orig. BTs., good condition, scribing visible, check for
bearings & distances.
The S.E. BT. Orig. bark scribed. I open S.W. BT, good scribe marks.
Set Brass Cap at corner marked $\frac{1}{4}$ S6/S5 T32S R3W County Surveyor's
Office, 1957.
I Scribe 10" Pine N.23°W. 22.2 ft. $\frac{1}{4}$ S6 CS BT.
I Rebark scribe Orig. BT. 36" Fir, now 48", $\frac{1}{4}$ S5 CS BT S.80°E. 5.3 ft. (
(measured to face.)

James W. Byron, Deputy County Surveyor
For Douglas County Road Dept.
Jan. & Feb. 1957
Rd. Drawer No. 48/Rd. #36

Section Corner Common to Sections 3, 4, 9, & 10. 30
Found 2" I.P. at Corner. The N.70°E. 14 lks. BT. alive & fair Ren. #1
condition. All other BTs. are dead. 64
Blaze & Scribe: 22" Yewwood bears S. 2°E. 184.4 ft. S10 T32S R3W CS BT.
26" W. Fir bears S89 1/2°W. 140.0 ft. S9 T32S R3W CS BT.
21" W. Fir bears N.44 1/2°W. 96.8 ft. S4 T32S R3W CS BT.

Closing Corner to Sections 1 & 12., as det. by O.B.T. 31
28" Fir bears S.23°W. 56.7 ft., found scribe. (This tree is being
removed for new road construction.) 58
At Corner Point found original Stone & Set Iron Pipe from which:
12" Fir bears N.3°W. 6.8 ft. dist mkd. S1 T32S B.T.
9" Fir bears S.84°W. 14.6 ft. dist. mkd. S12 T32 S R3W B.T.
Road bears South 56.0 ft. distance.

J. H. Markham, Jr.
Wit. R. G. Boyd
For: Stomar Lbr. Co
May 1, 1958
C. S. 42/356

$\frac{1}{4}$ Section Corner to Sections 14 & 15., as determined by O.B.T. 32
16" Hemlock windfall bears S.70°W. 14.5 ft. dist. O.B.T.,
found scribe.
At Corner Point found Stone Mkd: $\frac{1}{4}$ and
Set 1" x 30" Iron Pipe from which:
16" W. Fir bears S.2°E. 13.1 ft. dist. mkd: $\frac{1}{4}$ S14 T32S R3W B.T.
5" Yew bears S.70°W. 38.0 ft. dist. mkd. $\frac{1}{4}$ S15 B.T.
8" Yew bears S.40°W. 56.4 ft. dist. mkd. $\frac{1}{4}$ S15 R3W B.T.
Creek bears South 28.0 ft.
Road bears North 56.0 ft. SEE CORNER NO. 36

J. H. Markham, Jr.
Wit. H. C. Stokes
S. L. Brown.
For M. & B. Logging Co.
June 26, 1958
C. S. File No. 42/378