

Douglas County Surveyor's Record of  
Government Corners Renewed

32 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

33

Section Corner to Sections 1, 2, 11, & 12.  
Found - Orig. 20" x 10" x 5" Stone 15" in the ground & marked  
as recorded.

Now 48" Fir down & mostly rotted that checks bearing &  
distance for Original N.W. BT., no scribing found.

No trace of other BT's. found. The S.W. BT. may have  
been washed out.

The N.E. & S.E. BT's. would be in field.

Set Brass Cap alongside Corner Stone Mkd: County Surveyor's Office,  
1959 

S 2	S 1
S 11	S 12

 T32S R3W

Note - Corner under N.S. Fence.

New BT's: 16" Hemlock bears S. 2°W. 91.1 ft. scribed S11 T32S R3W CS BT.

18" R. Fir bears N.86°W.203.9 ft. scribed S 2 T32S R3W CS BT.

12" W. Fir bears S.20°E.263.6 ft. scribed S12 T32S R3W CS BT.

--- FOUND O.K. 1-9-69 J.M.P. ~~see 65/120 wq. cs. #~~

$\frac{1}{4}$  Section Corner to Sections 2 & 3.

Found - Orig. 36", now 44" R. Fir N.25°W. 9.2 ft., bark scribed " $\frac{1}{4}$ ".

Stump of Orig. Laurel, center rotted, shows old scar, S.60°E. 11.9ft.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

$\frac{1}{4}$  S3/S2 T 32 S R 3 W.

New BT's: 12" R. Fir bears S.63 $\frac{1}{2}$ °E. 32.9 ft. scribed  $\frac{1}{4}$  S 2 CS BT.

15" R. Fir bears S.42°W. 29.0 ft. scribed  $\frac{1}{4}$  S 3 CS BT.

$\frac{1}{4}$  Section Corner to Sections 1 & 12.

Found - Original 7", now 9" Fir Snag S.36°W. 6.6 ft., previously  
opened, shows good scribing " $\frac{1}{4}$  S12."

Orig. N.E. BT. would be under road fill.

Note - Corner Stone would be under 6' road fill. I do not search  
for it. I find  $\frac{3}{4}$ " Iron Rod with Stake Mkd: " $\frac{1}{4}$  Corner "  
which bears N.57°E. 6.2 ft. from Brass Cap.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959 69

$\frac{1}{4}$ 

S 1
S 12

 T 32 S R 3 W

New BT's: 16" R. Fir bears N.85 $\frac{1}{2}$ °E. 42.2 ft. scribed  $\frac{1}{4}$  S 1 CS BT.

17" R. Fir bears S.54°E. 93.5 ft. scribed  $\frac{1}{4}$  S12 CS BT.

35

$\frac{1}{4}$  Section Corner to Sections 14 and 15, as determined by O. B. T.:

16" W. Fir Stump(logged) bears S.2°E. 13.1 ft. dist., Ren. #32

O. B. T., found scribe.

All other BT's. gone.

At Corner Point Set  $1\frac{1}{4}$ " x 36" Truck Axle with flange up, from which:

13" W. Fir bears N.23°W. 151.7 ft. dist. mkd.  $\frac{1}{4}$  S15 B.T.

10" Yew bears S.58°E. 142.5 ft. dist. mkd.  $\frac{1}{4}$  S14 T32S B.T.

14" W. Fir bears S.49°E. 176.0 ft. dist. mkd.  $\frac{1}{4}$  S14 B.T.

Corner lies on West edge of Logging Road and 25 feet North of Creek.

SEE CORNERS 17-A & 18-A (E)

$\frac{1}{4}$  Corner to Sections 23 and 26, as det. by O.B.T.'s:

42" Fir N.50°E. 50.0 ft. O.B.T.

36" Cedar S.37°W. 22.0 ft. O.B.T.

At Corner Point Set 1" X 30" Iron Pipe and Found Stone, from which:

6" W. Fir bears S.69°E. 8.3 ft. dist. mkd.  $\frac{1}{4}$  S26 B.T. 81

10" Fir bears N.71°E. 9.0 ft. dist. mkd.  $\frac{1}{4}$  S23 B.T.

Road bears West 272.0 feet.

N. W. Corner Section 24, as det. by O.B.T.

36" Fir Stump, logged, bears S.55°E. 12.5 ft. O. B. T.

I rescribed S24 on top & B.T. on bark.

At Corner Point Set Truck Axle with flange up from which:

10" W. Fir bears S.46°E. 68.0 ft. dist. mkd. S24 B.T.

12" Fir bears S.68°E. 144.0 ft. dist. mkd. S24 B.T.

Road bears East 165.0 ft.

13  
23/24 FOUND O.K. 8/5/69  
J.M.P.

Wit. S. J. Pritchett - 11/9/58

38

James W. Byron, Deputy  
Milo Godfrey  
S. A. Billow  
February 24, 1959  
C. S. File No. 49/136

John H. Markham, Jr.  
For Stomar Lumber Co.  
Wit: J.L. Markham  
August 18, 1959  
C. S. File No. 42/356

James M. J. H. Markham, Jr.  
Milo Godfrey  
S. A. Billow  
February 17, 1959  
C. S. File No. 42/356