

Douglas County Surveyor's Record of
Government Corners Renewed

32

T. S.

3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

West 1/4 Corner Section 19, T32-2. only.

Found - 22" Fir, bears N.44°E., 26 lks., scribe visible.
12 x 8 x 4" Stone "S" marked on top.

Set - 2" x 30" Galv. I.P. with Brass Cap stamped:
1/4 Cor. S. 19, 1969 O.L.S. 536.

Found - 18" Fir, bears S.85°E., 12 lks., scribe visible.

Scribed: 12" Hemlock, bears S.80°E., 23.8 ft. Tagged.

Note - 1/4 Corner to Section 24, T32-3, Brass cap & original stone
bears S.1°03'55" W., 612.95 ft.

164

Glenn Baughman
For Umpqua
National Forest
July, 1969
M 38 - 38

1/4 Corner for Sec. 22 only. North boundary.

Set - 36" long, 2 1/2" gal. I.P. 32" in the ground, in a mound
of stones, with a 4" Brass cap mkd:

-1/4 S 22
T32S R3W
RLS 536 1974

Mkd. BT's - A 15" Cedar, bears S.77 W., 10.3 ft., scribed
1/4 S22 (BT) with a brass washer stamped RLS 536.

A 26" D. Fir, bears S.35 E., 63.6 ft. scribed 1/4
S 22 (BT) with a brass washer stamped RLS 536.

Note - This corner was destroyed in 1913 by Fred Mensch under
General Land Office Group #14. Surveyor General Record
states "I reestablished this corner at its orig. position
for Section 15 only as follows: Set a basalt stone,
15x10x5" 10" in the ground, for 1/4 Sec. Cor. for Sec.
15 only, mkd. 1/4 on North face: from which a Fir, 24"
bears N.37 E., 25 lks. dist. mkd. 1/4 S15 BT. A Fir,
20", bears N.30 W., 37 lks. dist. mkd. 1/4 S15 BT.

I destroy the marks on the bearing tree south of line.
Corner lies on gradual Southwest slope, approx. 200 ft.
Northeast of creek.

165

Center 1/4 Corner for Section 22.

Set - 36" long, 2 1/2" Gal. I.P. 32" in the ground, in a mound
of stones, with a 4" brass cap mkd:

T32S R3W
C 1/4 S22
RLS 536 1974

BT's - A White fir, 10", bears S.56 W., 9.4 ft. scribed C 1/4
S 22 (BT) with brass washer stamped RLS 536.

A Madrona, 13", bears N. 48 E., 10.6 ft. scribed C 1/4
S 22 (BT) with a brass washer stamped RLS 536.

166

Corner No.8 of H.E.S. # 186

Found: 30" Fir stump with visible scribe "BT" on N.E. face
Bears S 13°W., 15.2 ft.

Rotted stump with no visible scribe bears N 72°E.,
30.4 ft. No sign of original stone.

New: Set Brass cap on 1 1/2" Iron Pipe stamped
Douglas Co Surveyor T 32S R3W
1975 Cor.8

+
HES 186

From Which: A 8" Pine scribed "T32S R3W 8 HES 186 CS BT" in a
Double Blaze bears S89 1/2E., 19.1ft. A 10" Pine
scribed "T32S R3W 8 HES CS BT" in a double blaze
bears S28°W., 15.4 ft. Compass Declination 20°

Clell Goodv
Vic Cangie
Lenora Ladi
C.S. 57/30
6/12/75

167

Corner No. 11 of H.E.S. # 186

Found: 26" Fir stump with visible scribe "X11 HES 186 BT"
on the NE face bears N.12°W., 23.8 ft.

No. sign of the original stone

Set: Brass cap on 1 1/2" Iron pipe Stamped
DOUGLAS CO. SURVEYOR T32S R3W
1975 Cor 11

+
HES 186

From which: A 8" Pine scribed "T32S R3W 11 HES 186 CS BT" in
double blaze bears S84°E., 30.2ft.

(Cont. to next page)

Glenn Baughman Engineer
For U.S. Forest Service
M 49 - 69 and C.S. 55/357
July 18, 1974
Tiller Land Survey #13, Contract #004346N

JAN '75

SEE REN #169