

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 4 R. W. W. M.

Sept. 23, 1940
Arthur Boyer
Ted Shellebarger
Dick Dehrrig

Set by
Geo. J. Wenderoth
Reg. Land Surveyor #5.
August 6, 1944.
Wit. (

H.L. Eppstein
Wit.
James Richer
N.E. Richardson
Feb. 2, 1939
Dec 17 1916

C.E. Roberts
July 1910.

Set by B.A. Lane
Wit.
July 1937.

✓ E. $\frac{1}{2}$ Cor. Sec. 1, T. 323. R. 4 W. W. M. (SAME AS #10) 1
Set this corner from orig. Fir B.T. (10") which is N. 68°E.
8 links. The orig. 8" chinquapin S. 65°W. 4 links, is entirely
destroyed. Set a 4 x 4 chinquapin post and marked a new 24"
fir B. T. N. 48°W. 12 ft. marked $\frac{1}{4}$ S 1, T. 32 S. R.4W. C.S. B.T.

RE-RENEWED, SEE CORNER NO. 48

✓ SOUTHWEST CORNER SECTION 7. (7, 19, 12 + 13) 2
Set $\frac{1}{2}$ " x 38" I.P. at edge of Roadbed. SAME AS #53
Found stumps of 2 old bearing trees.
Marked 2 new trees no others available.
10" Fir S. 60° 35' E. 60.3 ft.
9" Live Oak N. 4° 06' E. 105.8 ft.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 7 AND 18. 3
Set $\frac{1}{2}$ " x 36" I.P.
Found stump of old bearing tree scribed other tree scrib
marks burned off.
Marked 2 new bearing trees.
12" Fir N. 89° 52' E. 39.8 ft.
24" pine S. 23° 17' E. 21.0 ft.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 20 and 21. 4
Reset. One Government Witness tree in evidence. Set
in Green Stone 8" x 8" x 16" marked with $\frac{1}{4}$ S. from which
A Red Fir 8" dia. bears N. 59° 30' W., 3.3 ft.
A Red Fir 5" dia. bears S. 89° 00' E., 15.4 ft.
Trees are marked according to law.
Set 1" I.P. for corner. G. J. Wenderoth May 1947 M. B. Germond Co. Sur.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 32 and 33. (But 1948) 5
Reset from old witness trees. Set stone 14" x 10" x 8".
Remarked old witness trees, as follows
A Fir 36" dia. N. 48° E., 25 links
A Fir 30" dia. S. 82° W., 48 links
Marked new witness tree
A Fir 40" dia. S. 5° W., 47 links.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 5 and 6. 6
Fir 12" dia. bears S. 14° E., 71 lks. marked C.S. 13
Fir 10" dia. bears S. 21° W., 74 lks. marked C.S.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 6 and 7. 7
Set New Wood Post 4" square marked N. 48° E. 3.3 ft.
Fir 5" dia. bears S. 26° W., 14 lks.
Pine 8" dia. bears N. 48° W., 74 lks. SEE ALSO # 55

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 22 and 23. 8
Set a Post from old B.T.s. Laurel rotted and Fir down
marked visible. Marked new B.T.
A 16" Fir N. 71 $\frac{1}{2}$ ° E., 33.0 ft. marked $\frac{1}{4}$ S. C.S.B.T.
A 30" Fir S. 18 $\frac{1}{2}$ ° W., 27.0 ft. marked $\frac{1}{4}$ S. C.S.B.T.

✓ SECTION CORNER BETWEEN 22, 23, 26 and 27. 9
Set Post, from old B.T. B.T. in good shape except
tree in S.E. quadrant down. Marked New B.T.
A 30" Fir S. 13° E., 24 1/5 ft. S. 27 C.S.B.T.