Douglas County Surveyor's Record of Government Corners Renewed

32 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

83

C. Corner to Sections 30 & 31. (on East line T 32 - 5 W)

Found - Madrone (now 13" diam) S 62° E 24.4 ft. Partial scribing visible on partly rotted face.
Rotten Fir stump N. 48° E 13.2 ft. Found good reverse scribing "BT" on decayed overgrowth of old face.

Set - Brass Cap mkd: "County Surveyor's Office 1964 T 32 S
R 5 W | S 30 R 4 W
S 31
C.C.

New BTs: 14" Madron N. 8° E 16.5 ft. Mkd: "T 32 SR 4 W S 30 CC CS BT"
4" Doug. Fir S. 73°E 13.5 ft. Mkd: "CC S 31 CS BT"
19" Live Oak S. 9° W. 20.0 ft. Mkd: "CC S 30 S 31 CS BT"
Corner lies directly on top of ridge.

Milo E. Godfrey, Deputy
Mike Stone
June, 1964
C. S. File No. 53/52

84

C. Corner to Sections 25 & 36. (On West line T. 32 S R 4 W)

Found - Yew wood stake set by Wenderoth. Scribed "CS" (Ren # 85)32-5
Doug. Fir (now 15" diam). N. 38° W 39.7 ft (to face). Both axe scars very plain but healed over. Tree in good condition.
Wenderoth's S.W. tree is now dead & down.-Scribing visible.
Stump of original S.W. tree & burned remains of original N.W. tree.

Set - Brass Cap mkd. "County Surveyors Office 1964 T 32 SR 5 W
CC S 25 | R 4 W"-reset yew post alongside.
S 36

New BT: 5" White fir S. 73° W 14.0 ft. Mkd: "CC S 36 CS BT".

85

S. W. Corner to Section 31.
(on E. & N. lines of Sec 1. T. 33 S.R. 5 W)

Found - Doug. Fir (now 21" diam.) N. 47° E. 21.1 ft. Fragmentary scribing visible on partially rotted face.
Did not find marked rock at corner.

Set - Brass Cap mkd: " County Surveyor's Office 1964
T 32 S " Erect rock mound around pipe.
R | R
5 S31 4
W S1 W
T 33 S

Rescribe: 21" Doug. Fir N. 47° E. 21.1 ft. Mkd: "T 32 SR 4 W S 31 CS BT"
New BTs: 9" Doug. Fir S. 44° E. 11.2 ft. Mkd: "T 33 SR 5 W S 1 CS BT"
Corner lies on very rocky, very steep, NW slope.

86

Corner to Sections 1 & 36.
(on W. line Sec 31 T. 32 S. R 4 W)

Found - Doug. Fir (now 24" diam.) S. 60° W. 11.2 ft. Scribing visible on partly exposed face "R 5W" tree alive & in good condition.
Doug. Fir. (now 23" diam.) N. 62° W. 13.2 ft. Previously opened but nearly healed over-now scribing visible-tree in good condition.
Doug. Fir (now 26" diam.) N. 42° E. 21.8 ft. (not 17.8 ft) scribing visible on partially exposed face "S 31"-tree in good condition.
Partly rotten cedar stump S. 58° E. 25.7 ft. Scribing visible "R 4 W T 33 S S 6"

Set - Brass Cap mke: "County Surveyor's Office 1964
T 32 S
R S36 S R
5 S 1 31 4
W W

Did not mark any new trees.

Milo E. Godfrey, Dep. Surv.
Wm. Stoffel, Mike Darby, Mike Stone
June, 1964
C. S. File No. 53/52

Fd. O. K. by:
L. D. SMITH
MAY 14, 1982
M 92-34