


Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

Closing Corner to Sections 1 & 6. (7.35 S.)

87

Found - Rock ~~as~~ described, in mound of rocks.
Fir snag N. 46° E. 15.8 ft. Scribing visible "T 33 SR 4 & 5W
S 1 & 6 BT"
Fir snag S. 77° E. 10.6 ft. Part of face exposed, but no
scribing visible.
Doug. Fir (now 15" diam.) S. 39° W. 26.4 ft. Scribing
visible on previously opened face. "3SR 5 W S 1"-Tree in
good condition. A vertical rock cliff approx. 10 ft.
high between this tree and corner.
Set - Brass Cap (on top of bedrock) Mkd: "County Surveyor's Office
1964 T. 32 S " Cap not oriented correctly
R S31 R thus- 
5 S1 | S6 4
W W
T 33 S
New BT: 9" Doug. Fir S. 65° E. 25.0 ft. Mkd: "T 33 SR 4 W. S 6 CS BT"
Corner lies on very steep, rocky NW slope.

Dep.
Milo E. Godfrey, Co. Surv.
Wm. Stoffel, Mike Darby, Mike Stone
June, 1964
C. S. File No. 53/52

FD I. R.
10/93 BY P. ROGERS
P93-0082

CENTER 1/4 Corner of Section 5.
Re-Set 5/8" I. Rod from Old BT's. See Ren. #81.
12" D. Fir S. 17° W. 23.7 ft.
16" D. Fir N. 49° W. 74.3 ft.

88

January 1965

Bruce A. Shaner
For G. Hildebrandt
Map File
M 22 - 62

1/4 Corner to Sections 7 and 18.

89

Found - Stump of Fir BT. N. 89, 52' E. 39.8 ft., scribed.
Stump Pine S. 23, 17' E. 21 ft. (Cut years ago) ^{See #3!}
3/4" Iron Pipe, badly bent from logging. ⁵⁴
Set - Brass Cap at Corner, from which:
10" Fir N. 43, 25, W. 31.2 ft.
24" Fir S. 1, E., 40.1 ft.

Geo. J. Wenderoth
For - J. F. ^{er}
May 1965
C. S. File
No. 54/5

1/4 Corner to Sections 3 and 4.

90

Found - BLM Brass Cap, Mkd. 1/4 S 4, 1960.
All BT's. in good condition.
(Correspondence concerning this corner, See BLM Letter File)
Set - Brass Cap alongside BLM Cap Mkd: 1/4 S 4 T32S R4W
County Surveyor's Off. 1965
New BT's: 10" Fir bears S. 21° W. 37.3 ft. Mkd: E 1/4 S 4 CS BT.

Bruce R. Rogers, Deputy
For Doug. Co.
Park Dept.
June 1965
M 29 - 78

Wit. Cor. 1/4 Corner to Sec. 1, T32-4W. and Sec. 36, T31-4W.

91

Found - No trace of I. Red set in Ren. #46 This corner was
in horse lot, owners wanted it reset outside lot.
48" Cedar, now 50", S. 57° W. 170.0 ft. "BT" scribe visible.
18" Fir N. 48° E. 130.4 ft. This tree is dead, shows good
pitched over scars. T 31 S
Set - Brass Cap for With. Cor. Mkd: W.C. 8' S. to 1/4 S 36
County Surveyor's R4W S 1
Office, 1966 T 32 S
New BT: 7" Cedar N. 79 1/2° E. 37.0 ft. Mkd: 1/4 S 36 CS BT.
Note - Brass Cap in E. W. Wood Fence.

John M. Powell &
Crew
Jan. 17, 1966
C. S. File
No. 54/20

BOOK BROWN
BY 4-93
MIL-2

~~Sec. Cor. to Sec. 36, T32-4; Sec. 25, T31-4; Sec. 30, T31-3; & Sec. 31, T32-3.~~

92

~~Found - 24" Cedar, now dead snag, S. 7° W. 20.6 ft. scribe visible "CS BT".
20" D. Fir, now 25", N. 13 1/2° E. 22.7 ft. Tree in slope bank of road.
14" D. Fir, now 17", N. 13° W. 19.4 ft., shows good scar.
18" D. Fir S. E., gone. (All BT's. above shown Ren. #19, T31-3W.)
Set - Brass Cap at Sec. Cor. Mkd: T31S R4W RECORDED R3W
County Surveyor's T32S S 36 | S 31
Office, 1966 OOT 1966 WROKNG
New BT's: 19" D. Fir S. 16° E. 80.1 ft. scribed T32SR3WS31 CS BT.
8" D. Fir S. 83° W. 17.5 ft. scribed T32SR4W CS BT.
This corner is on edge of New Road.~~

John M. Powell
F. Jones & J. Brady
Jan. 13, 1966
C. S. File No. 52/63