

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Wenderoth,  
Geo. J.  
C. S. File  
No.  
38/246

Center of Section 20.  
Found - 1" Iron Pipe set in 1948 for Macco Lumber Co.  
5", now 10" Chinquapin, N. 21°W. 29.2 ft.  
Marked: 11" Fir S. 84° 40' E. 19.7 feet. Sept. 1969

105

1/4 Corner to Section 27 and 28.  
Found - 24", now 28" Orig. D. Fir N. 83°W. 7 lks., blown down.  
I opened the face additionally & found the scribing "1/4 S".  
Orig. 20", now 24" D. Fir, N. 50°E. 6 lks., good condition.  
Upper face opened about 1954 but couldn't read any scribing.  
Opened lower, chopped in 2-3", and found the scribing "1/4 S".  
Set - 3/4" x 32" Iron Pipe  
Scribed - 16" Yew Wood, S. 14 1/2°W. 29.2 ft. mkd: T32S R4W S 28 RS841 BT.

106

1/4 Corner to Sections 28 and 33.  
Found - Orig. 40" D. Fir, now 40" low cut stump, N. 63°W. 15 lks.  
opened prior to logging, about 1955, and some scribing remains  
on the stump and on a piece of wood layed by the stump, "1/4".  
Set - 3/4" x 32" Iron Pipe  
Scribed: - 10" Madrone, N. 19 1/2°E. 16.6 ft. mkd: T32S R4W S28 RS841 BT.  
5" Madrone, S. 78°W. 11.0 ft. mkd: T32S R4W S33 RS841 BT.

107

Section Corner to Sections 27 - 28 - 33 - 34.  
Found - Remains of Orig. Dead D. Fir, 14", S. 86°E. 44 lks., The snag  
had broken off at the ground and left a distinct stump, scribing  
on the felled portion "S34 BT". Using the above bear. & dist.,  
the pipe was set.  
Set - 3/4" x 32" Iron Pipe  
Scribed - 11 1/2" D. Fir, S. 41°E. 50.1 ft. mkd: T32S R4W S34 RS841 BT.  
9" D. Fir N. 19°E. 48.5 ft. mkd: T32S R4W S27 RS841 BT.  
12" D. Fir N. 45°W. 71.7 ft. mkd: T32S R4W S28 RS841 BT.  
4" Live Oak, S. 40°W. 36.2 ft. mkd: S33 BT.

108

Lorne V.  
Swearingen  
S. Ore. Ply.  
C. S. File  
No.  
55/85

Closing Corner for Sections 18 & 19, T32-3W.  
Found - Cadastral Brass Cap, properly marked in 1959.  
The bearing tree for Sec. 18 was in good shape & the BT. for  
Sec. 19 was fell with stump remaining on a very high cut bank of new road  
construction. Because of the very high cut bank and the inaccessability  
of reasonably close bearing trees, and the fact that there will be a  
possibility of a future timber sale in Section 19, I scribed the following  
Bearing Trees: 7" Hemlock S. 38° W. 21.1 ft. mkd: "T32S R4W S24".

109

1/4 Corner to Sections 28 and 21.  
Found - 20" D. Fir, now stump, N. 75°E. 29.0 ft., opened for scribe "T".  
24" D. Fir, now stump, S. 87°E. 23.8 ft., opened earlier, scribe vis.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 4 W  
Office 1/4 S 21  
1970 S 28  
New BT's: 5" Live Oak N. 62 1/2°E. 25.5 ft. mkd: "1/4 S21 CS BT.  
5" Live Oak N. 2° E. 38.0 ft. mkd: "1/4 S21 CS BT.  
This corner lies in logged unit, no other BT's. available.

110

1/4 Corner to Sections 16 and 21.  
Found - 30", now 38" D. Fir, N. 69°E. 23.8 ft., opened for scribe "1/4".  
36", now 46" D. Fir, S. 17°E. 16.5 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 4 W  
Office S 16  
1970 S 21  
Reblzd. & Resbd: 38" D. Fir N. 69°E. 23.8 ft. mkd: 2" 1/4 S16 CS BT.

111

John M. Powell  
W. Penley & J. Heritage  
C. S. File No. 54/114

5/6/70