

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

125

Closing Corner to Section 4 & 5, T33-4W.

Found - 10", now 13" Cedar, N.27°E. (Rec. N22E) 5.3 ft., scribe visible.
18", now 22" Cedar, S.64°E. 5.3 ft., scribe visible.
6", now 9" D. Fir, S.63°W. 24.4 ft., shows good scar.
24x12x8 Stone, mkd: "CC".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T32S R4W CC S 33
T33S R4W CC S 5 | S 4
1970

New BT: 22" Laurel N.55°W. 14.5 ft. mkd: "T32S R4W S33 CS BT."
All other BT's. O. K. and Tagged.

This corner lies about 70.0 ft. west of ravine.

5/15/70

126

Closing Corner to Sections 33 & 34, T32-4W.

Found - 30" Fir, now snag, N.37°W. 20.0 ft., scribe visible, burnt face.
No trace of other bearing trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office Doug. Co. T32S R4W CC S 33 | S 34
1970 T33S R4W CC S 4
Jack. Co.

New BT's: 4" D. Fir N.20°E. 9.7 ft. mkd: "S34 CC CS BT."
8" D. Fir S. 4°E. 14.5 ft. mkd: "T33S R4W S4 CS BT".
10" D. Fir N.64°W. 42.5 ft. mkd: "T32S R4W S33 CC CS BT."

This corner lies on small spur, running south.

5/8/70

127

Standard Section Corner to Secs. 32 & 33 only, T32-4W.

Found - 40", now 40" Cedar, N.65°W. 17.2 ft., opened for scribe.
No trace of N. E. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T32S R4W S SC S 32 | S 33
1970 T33S R4W S 4

Rblzd. & Rscbd: 40" Cedar N.65°W. 17.2 ft. mkd: "T32S R4W S SC S32 CS BT."
New BT: 24" Cedar N.80°E. 69.8 ft. mkd: "T32S R4W S SC S33 CS BT".

5/14/70

128

Standard $\frac{1}{4}$ Corner to Section 33, T32-4W.

Found - 12" Cedar (Rec. Fir), now 20", S.50°W. 16.5 ft., opened for scribe.
(Ring Count places age approx. 1885)
6" Fir, down rotten, N.45°W. 4.0 ft., has very old rotten
face, maybe very faint scribe.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office Doug. Co. T32S R4W S 33
1970 T33S R4W S $\frac{1}{4}$ C
Jack. Co.

New BT's: 38" D. Fir N.52°E. 15.6 ft. mkd: "S $\frac{1}{4}$ C S33 CS BT".
12" D. Fir N.38°W. 12.7 ft. mkd: "S $\frac{1}{4}$ C S33 CS BT".

By pacing, corner hits approx. 9 chains west of C.C. Cor. S33/S34 &
3 chains east of ridge.

5/14/70

129

Standard $\frac{1}{4}$ Corner to Section 32, T32-4W.

Found - 16", now 24" Cedar, S.45°E. 16.5 ft., opened for scribe, burnt
& rotted face, but found definite reverse scribing.
20" D. Fir, now stump, N.68°W. 6.6 ft., no marks found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office T32S R4W S $\frac{1}{4}$ C S 32
1970 T33S R4W S $\frac{1}{4}$ C

New BT's: 14" D. Fir N.15°W. 30.6 ft. mkd: "S $\frac{1}{4}$ C S32 CS BT".
8" D. Fir S.61°E. 18.4 ft. mkd: "S $\frac{1}{4}$ C CS BT".

5/15/70

130

Standard Section Corner to Sections 33 and 34, T32-4W.

Found - No trace of N. W. BT.
18" D. Fir, now dead stob, N.45°E. 12.5 ft., upper face open, old
rotten scribe visible, "S" & other marks.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office Doug. Co. T32S R4W S 33 | S 34
1970 T33S R4W S. SC.
Jack. Co.

New BT's: 24" D. Fir N.48°E. 19.5 ft. mkd: "T32S R4W S SC S34 CS BT".
32" D. Fir N. 8°W. 21.4 ft. mkd: "T32S R4W S SC S33 CS BT".

This corner lies approx. 125.0 ft. west of draw.

5/19/90

John M. Powell
W. Penley & J. Heritage
C.S. File No. 54/114