

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHARMAN CO., EUGENE, ORE. 21801

131

Closing Corner to Sections 32 and 33, T32-4W.

Found - No trace of Stone Monument.

14", now 21" D. Fir, N. 18° E. 20.5 ft., scribing visible on burnt face.

24", now 30" D. Fir, N. 17° W. 16.5 ft., shows good scar. O. K.

Set - Brass Cap at Cor. Mkd: County Surveyor's T32S R4W C.C. S 32 | S 33
Office, 1970 T33S S 5

Reblzd. & Resbd: 21" D. Fir N. 18° E. 20.5 ft. mkd: "T32SR4WCC S33 CS BT".
5/19/70

132

Standard 1/4 Corner to Section 31, T32-4W.

Found - 18" D. Fir, now stob, N. 30° W. (Rec. N30E) 15.7 ft. (Rec. 12.9),
scribe visible.

18" D. Fir, now stob, S. 27° W. 11.9 ft., scribe visible.

By facing up trees, I assume southerly tree to be correct. Also from this
BT, I hit old E-W blazed line.

Set - Brass Cap at Cor. Mkd: County Surveyor's T32S R4W S 31
Office, 1970 T33S S 1/4 C

New BT's: 6" D. Fir N. 39° E. 12.5 ft. mkd: "S 1/4 C S31 CS BT".

6" D. Fir N. 26° W. 28.2 ft. mkd: "S 1/4 C S31 CS BT".

Approx. 1.5 ft. from this point there is an old mound of stones, not called
for in notes, but look like they were put there.

5/22/70

133

1/4 Corner to Sections 29 and 30.

Found - Cadastral Brass Cap on this corner is intact.

28" D. F., N. 88° 45' E. 39.5 ft., in good condition, now slightly
covered with road fill.

46" D. F., S. 04° W. 59 ft., removed for road construction.

Scribed: 7" D. F. N10W. 34.9 ft. mkd: "1/4 S, T32S R4W RS 841 B.T. 7/27/70

134

1/4 Corner to Sections 2 and 11.

Found - Orig. 24", now 56" Cedar, N. 20° W. 20.5 ft., tree opened,
scribe visible "S".

No trace of Orig. Laurel BT.

Lecklider's BT's. See M 15 - 31, and Ren. #72.

16" D. Fir N. 75° E. 19.8 ft. (Rec. 16.1) shows good scars.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's T 32 S R 4 W
Office 1/4 S 2
1971 S 11

Bearing Trees O. K., Tagged same.

1/29/71

135

Center of Section 4.

Set - 1" Iron Pipe with 2 1/2" Brass Cap Stamped:

T 32 S R 4 W C 1/4 S 4

from which:

A 7" D. Fir scribed C 1/4 S 4 BT bears N. 86° W. 25.8 ft.

A 12" D. Fir scribed C 1/4 S 4 BT bears S. 37° E. 50.3 ft.

Sept. '71

136

Angle Point Corner common to Sections 36 & 31 T. 32S R4 & 5W.

Original corner 30, 31, 25 and 36.

Original Post (missing) from which a:

8" Fir, bears S. 25° W., 18 lks.; missing.

12" Fir, bears S. 50° E., 73 lks.; missing (destroyed by Nicklin 1896),
root holes in place.

6" Fir, bears N. 66° E., 43 lks.; missing (destroyed by Nicklin 1896),
covered by fresh logging slash.

12" Hemlock bears N. 40° W., 20 lks.; missing.

1896 Post (missing) by Carl S. Nicklin.

1900 Hemlock post (missing) by Oscar Thiel from which a:

24" Fir, bears N. 22° E., 86 lks.; now 16" x 10' rotten stub, in place,
no face.

40" Fir, bears S. 83° E., 12 lks.; now 46" windfall snag, found back cast
B and scribes SW.

17" White Fir (not recorded), bears N. 56° W., 54.0 ft.; face opened,
scribes T32 S R5W S visible at 50 years.

Set - 1 1/2" x 36" galv. iron pipe with 3" bronze cap marked "OREGON STATE BD.
OF FORESTRY AP T32S S36 R5W T32S S31 R4W 1972 RS 359", 34" in ground, and
from which a:

cont.

John M. Powell
W. Penley & J. Heritage
C.S. File No. 54/114

Ronald A. Brandt
For: Robert Dollar Co.
C.S. 55/129

John M. Powell
W. Penley & J. Heritage
C.S. 54/114

By Victor M. McLind
For: Lingenfelder
Map File
M 43 - 57

JAN. 1972

Oregon State Board of Forestry
Arnold Gibson
Lloyd D. Smith
May, 30, 1972
C.S. File 55/233