

**Douglas County Surveyor's Record of  
Government Corners Renewed**

32

T. S.

4

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

157

James D. Artman  
For: Medford  
Corporation  
April 1990  
M 110 - 11

1/4 Corner for Sections 28 and 29  
Set - 5/8" x 30" iron rod with 1" plastic cap marked "ARTMAN RLS 2268"  
BTs - 9" live oak bears S.27°W., 20.2 ft. scribed "1/4 S29 BT"  
14" madrone bears S.20°E., 18.6 ft. scribed "1/4 S28 BT".  
15" D. fir bears N.35°E., 30.8 ft. scribed "1/4 S28 BT".  
6" D. fir bears N.45°W., 31.0 ft. scribed "1/4 S29 BT".

4/90

158

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Oct. 30, 1990  
C.S. 64/11

1/4 Corner for Section 17 only. (North)  
Found - A 3 1/2" dia. BLM brass cap on an iron pipe is found flush with ground. (1971)  
*FND OK 11/90*  
*M 111-12* A DCSO 1 1/2" O.D. flanged iron pipe is found inverted, protruding 15" above ground. Ren. #117. Inverted in 1971 BLM resurvey. DCSO I.P. bears North 0.5 ft. from BLM BC/IP.  
12" madrone now roothole with remains of decayed madrone along side, no blazes or scribing visible, root hole bears N.15°W., 7.3 ft. (agrees with record) Orig. BT.  
Orig. southeast BT is gone.  
38" now 42" dia. D. fir with a fully healed single blaze bears S.59°E., 31.3 ft. (agrees with rec) Ren. No. 117  
35" now 35" dia. 2 1/2" high D. fir stump, no blazes or scribing visible, bears S.18 1/2°W., 45.2 ft. (agrees w/rec) 1971 BLM resurvey.  
New BTs - 28" dia. 1 1/2 ft. high D. fir stump, set 8" boat spke through BT tag near top center of stump, stamped "B01" boat spike bears S.73°E., 68.4 ft.  
36" dia. 4 ft. high D. fir stump, set 8" boat spike through BT tag near top center of stump, stamped "B02", boat spike bears S.20°E., 49.0 ft.

Corner lies on a southerly slope in a new clear cut. Approx. 700 ft. north of gravel road.

1/4 Corner for Sections 5 and 8. 10/30/90

Kristian DeGroot  
L.S. 1941  
For: Roseburg Res.  
& S. Jantzer  
Nov. 1990  
M 111 - 12  
C.S. 63/52

Found - 5/8" iron rod firmly set, projecting 10" above ground as set by Shaner in 1963 per RM 1-37.  
BTs. - 36" D. fir bears S.70°W., 51.4 ft. with a healed blaze. 159  
*FD 31923 C40*  
*By Bruce Roberts*  
*10/93*  
*1993-0082* (record S.69°W.) Renewal No. 80.  
36" D. fir bears N.08°W., 60.8 ft. with a partially healed blaze.  
Set - Removed 5/8" iron rod and in its exact position set a 1"X30" iron pipe 18" in the ground in a 2 ft. diameter mound of stone with a 2 1/2" brass cap. Reset the 5/8" iron rod on the N. edge of the brass cap w/iron pipe. 11/90

1/4 Corner for Section 9 only. 160

Set - 1" X 30" iron pipe 24" in the ground with a 2 1/2" brass cap.  
BTs. - 38" D. fir bears N.85°E., 4.6 ft. with healed blaze. (original)  
21" D. fir bears N.85°W., 8.6 ft. with healed blaze. (original)  
11/90

1/4 Corner for Section 8 only. 161

Set - 1" X 30" iron pipe, 24" in the ground with brass cap marked " T32S R4W 1/4 S8 1990 PLS 1941"  
BTs - By Laurence in 1949 Renewal No. 28  
24" D. fir bears N.33°W., 32.4 ft. with healed blaze.  
54" D. fir bears S.55°W., 41.6 ft. with a healed blaze.  
11/90

Center 1/4 for Section 8. 162

Set - 1" X 30" iron pipe 24" in the ground with a 2 1/2" brass cap marked: "T32S R4W C 1/4 1990 PLS 1941"  
New BTs - 18" hemlock bears N.8 3/4°W., 26.9 ft. scribed "C 1/4 S 8 BT"  
14" hemlock bears N.86°W., 28.1 ft. scribed "C 1/4 S8 BT"  
Reference 5/8" iron rod w/alum. cap at the center east 1/16 cor. of  
Objects - section 8, bears N.89° 35' 25"E., 592.73 ft.  
5/8" iron rod w/alum. cap at the center south 1/16 cor. of section 8, bears S. 01° 10' 55"E., 669.18 ft.  
11/90