

**Douglas County Surveyor's Record of
Government Corners Renewed**

32 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Section Corner to Secs. 30 & 31, T32S R5W, & Secs. 25 & 36, T32S R6W.
Found - All BT's & Corner Tree as recorded by Theil, 1901. All are
now snags. All check for bearing & distances. Find good
scribing on all BT's., except S. E. BT. & it shows old &
rotted face.

I pull the Corner Tree Over & Set Brass Cap alongside Base Mkd: **115**
R6W

325	S30
S36	S31

 R5W T32S County Surveyor's Office, 1958 **154**

New BT's: 25" Cedar bears N.14°W. 69.5 ft. scribed S25 T32S R6W CS BT.
10" Cedar bears S.34°W. 72.1 ft. scribed S36 T32S R6W CS BT.
8" R.Fir bears S.80°E. 57.0 ft. scribed S31 T32S R5W CS BT.
8" R.Fir bears N.69°E. 80.1 ft. scribed S30 T32S R5W CS BT.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
September, 1958
C. S. File No. 49/915

$\frac{1}{4}$ Section Corner to Sec. 6 T32S R5W, & Sec. 1, T32S R6W. **116**
Found - 22" Fir West 13.2 ft.
Scribed - 24" Fir S.12°18'E. 18.2 ft.
14" Fir N.42°40'E. 20.1 ft.
Set $\frac{3}{4}$ " Iron Pipe for Corner.

George
Wenderoth
For C.&D.Lumber
April 11, 1959
C.S. File No.
49/92

$\frac{1}{4}$ Section Corner to Sec. 7, T32S R5W, & Sec. 12, T32S R6W. **117**
Found - Both Orig. BT's., each BT. not completely grown over,
show good scribing "BT" - "BT".

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
 $\frac{1}{4}$ S12/S 7 T32S
R6W R5W

Orig. BT's. are thus from corner:
44" Cedar bears S.11°E. 33.3 ft.
36" Cedar bears S.81°W. 16.8 ft.
I do not rescribe BT's.

James W. Byron, Deputy
Milo E. Godfrey
S. A. Bilow
June 24, 1959
C. S. File No. 49/91

Section Corner to Sec. 7 & 18, T32S R5W. & Sec. 12 & 13, T32S R6W. **118**
Find - 14", now 16" Fir Snag, shows old scar, center burned, no
scribing found. N.43°W. 19.8 ft. (scribed by Theil)
Orig. 12", now 24" Cedar S.24°E. 22.4 ft., center burned out,
does show good scribing "32 S T".
Orig. 9", now 18" Laurel N.34°E. 31.0 ft. shows good scribing,
"32S R5W S".

No trace of Orig. N. W. BT.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

R6W

S12	S 7
S13	S18

 T32S R5W

New BT's: 13" Fir bears N.32°E. 39.5 ft. scribed T32S R5W S 7 CS BT.
5" Laurel " N.52°W. 24.4 ft. scribed S12 CS BT.
12" R. Fir " S.58 $\frac{1}{2}$ °E. 51.6 ft. scribed S13 T32S R5W CS BT.
38" R.Fir " South 10.0 ft. scribed S13 T32S R6W.

Section Corner common to Sections 6, & 7 T32S R5W & Secs. 1 & 12, T32S R6W. **119**
Orig. - Cedar post, missing, from which a:

- 8" Cedar bears N.24°E. 59 lks.; now 8" rotten uproot,
faced, no scribes.
- 5" Cedar bears S.63°E. 34 lks.; missing.
- 7" Cedar bears S.24°W. 56 lks.; now 12" uproot, scribed T32S
R6W S12 visible.
- 8" Cedar bears N.36°W. 39 lks.; now 12" uproot, face burnt,
original axe work remaining on lower edge of face.
- 48" Line Tree 8.39 chains N, found 48" uproot in place.

Resurvey, July 1902: Cedar Post, missing from which a: 40" Fir bears
S.40°E. 27 lks.; now 42", portion of face visible in bark.

Restored - Set 1 $\frac{1}{2}$ " x 36" gal. I.P. with bronze cap Mkd: Ore. St. Bd. of
Forestry T32S R5W R6W/ S1 S6 S7 S12 1960 RE2311" 30" in gr.
9" Cedar bears N.26 $\frac{1}{2}$ °E. 82.6 ft.; scribed T32S R5W S6 BT.
23" Cedar bears N.67°W. 27.4 ft.; scribed T32S R6W S1BT RE2311.
26" Cedar bears S.34°W. 47.1 ft.; scribed T32S R6W S12 BT.
42" Fir bears S.28°E. 12.0 ft.; scribed T32S R5W S7 BT.

Ore. St. Bd. of Forestry metal location poster on 42" Fir BT.

Set 4"x4"x60" White painted Cedar post 2' NE of pipe.

Oregon St. Bd. of Forestry
Louis W. Amort
D. Bagger, Transitman
April 29, 1960
C.S. File No. 42/341