

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

Geo. Wenderoth
June 1962
C.S. File
52/123

$\frac{1}{4}$ Corner to Sections 20 and 29.
1" I. Pipe $\frac{1}{4}$ Corner.
16" Cottonwood S. $68^{\circ}30'W$. 14.1 ft.
10" Cottonwood N. $56^{\circ}47'W$. 43.2 ft.

REN # 27

SEE M99-33
REPORTS COR.
& ACCESSORIES
DESTROYED
BY CON CREEK

120.

Sec. Cor. T32S R6W S36/S31 R5W
T33S

121

Found - $1\frac{1}{2}$ " Axle at Corner & Large Fir Stump S. $37^{\circ}W$. 45.5 ft.
New BT's: 8" R. Fir N. $3^{\circ}30'W$. 15.4 ft. (scribed by R.E. 3024)
40" R. Fir N. $7^{\circ}E$. 42.0 ft. (3/19/68-Revisited Cor. & Fd. as
(recorded-Call to Ck. to W. checks record-Find 23" Laurel, center rotted, NE, BT)
(See Addn. Notes C.S. 49/112)

Fd. 8/90
M110-48

South $\frac{1}{4}$ Corner Section 31 only.

Set - By proportionate measurement.

Brass Cap at Cor. Mkd: County Surveyor's Office, 1958
South $\frac{1}{4}$ S31, T32S R5W

(SAME AS
#112)

New BT's: 10" R. Fir bears N. $37^{\circ}E$. 3.5 ft. scribed $\frac{1}{4}$ S31 CS BT.
10" Laurel bears N. $27^{\circ}30'W$. 33.2 ft. scribed $\frac{1}{4}$ S31 CS BT.

North $\frac{1}{4}$ Corner to Section 6, T33S, R5W.

123

Set by proportionate measurement.

Brass Cap at Cor. Mkd: County Surveyor's Office, 1958
 $\frac{1}{4}$ S 6 T33S R5W.

New BT's: 14" R. Fir bears S. $78^{\circ}W$. 20.5 ft. scribed $\frac{1}{4}$ S6 CS BT.
8" Laurel bears S. $40^{\circ}E$. 10.5 ft. scribed $\frac{1}{4}$ S6 CS BT.

Cl. Corner-Section Corner to Secs. 31 & 32 only, T32S R5W.

Found - Pipe at Corner and All Bearing Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1958
S31/S32 T32S R5W
S 5 T33S

SEE ALSO
REN #111

124

New BT: 5" W. Fir S. $65^{\circ}W$. 11.6 ft. scribed CC. S31 - 32 BT.
Note - Destroyed all evidence of Standard Corner.

BOTH CORNS.
O.K.
AUG. 1967

Sec. Cor. to Sections 6 and 5 only, T33-5W.

125

Found - Stone at Cor. & both Orig. BT's.

Set - Brass Cap at Cor. Mkd: S 6/S 5 T33S R5W County Surveyor's
Office, 1958.

New BT's: 24" Fir bears S. $12^{\circ}E$. 18.0 ft. scribed T33S R5W CC S5 CS BT.
6" Acorn^{Oak} bears S. $44^{\circ}W$. 12.2 ft. scribed T33S R5W CC S6 CS BT.

Geo. J.
Wenderoth
C. & D.
Lumber
C.S. 49/92

Township Corner

T31S
R6W S 36 | S 31 R5W
S 1 | S 6
T32S

126

Set - 1" Iron Pipe at Corner

Scribed - 52" Fir S. $35^{\circ}35'E$. 13.6 feet.
12" Hemlock S. $46^{\circ}12'W$. 32.2 feet.
16" Yew N. $79^{\circ}40'W$. 97.4 feet.

Red'd. Feb. 1964

$\frac{1}{4}$ Corner to ~~Sec. 6, T32-5W~~ & Sec. 31, T31-5W.

127

Orig- Post, now missing, from which a:

7" Fir bears N. $73^{\circ}W$. 24 lks.; 18" down rotted log, portion
of cast of scribe remaining.

6" Fir bears S. $35^{\circ}E$. 14 lks.; missing, burnt out.

Orig. (119 yr. old) line blazes on Township Line West.

67 yr. old line blazes on same line west and north.

Very old, burnt cruiser marks on large Firs in the SE, SW & NE.

X on down Cedar 34 feet West.

N. & S. Ridge 1s lks. E; in place. Ravine S. 2.28 ch. W.; in place.

Set - $1\frac{1}{2}$ " x 36" gal. I.P. with 3" br. cap Mkd: "Ore. St. Bd. of Forestry $\frac{1}{4}$ S31

S6 1964 RS 359", 30" in ground and from which a:

10" Fir bears S. $6\frac{1}{2}^{\circ}W$. 18.5 ft.; scribed $\frac{1}{4}$ S6 BT.

38" Fir bears N. $18\frac{1}{2}^{\circ}W$. 50.4 ft.; scribed $\frac{1}{4}$ S31 BT RS359.

Set 4x4x72" white painted Cedar Post 1.5 ft. NW. of corner pipe.

Ore. St. Forestry Dept. metal location poster on 24" Fir S. $12^{\circ}W$. 14.0 ft.

Ore. St. Bd. of Forestry
Arnold G. Gibson
Wit: D. Ray & R. Olson
April 7, 1964
C. S. File No. 51/264

RE-RENEWED. SEE CORNER NO. 139

ONLY 1/15/92