

Douglas County Surveyor's Record of  
Government Corners Renewed

32 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

132

S.W. Corner to Section 31. (7.32-4)

(on E. & N. lines of Sec 1, T. 33 S.R. 5 W)

Found - Doug. Fir (now 21" diam.) N. 47° E. 21.1 ft. Fragmentary scribing visible on partially rotted face.

Did not find marked rock at corner.

Set - Brass Cap mkd: "County Surveyor's Office 1964

T 32 S " Erect rock mound around pipe.

R S31 R

5 S1 4

WT 33 SW

Rescribe: 21" Doug. Fir N. 47° E. 21.1 ft. Mkd: "T 32SR 4 W S 31 CS BT"

New BT: 9" Doug. Fir S. 44° E. 11.2 ft. Mkd: "T 33SR 5 W S 1 CS BT"

Corner lies on very rock, very steep, NW slope.

-----  
Corner to Sections 1 & 36.

(on W. line Sec. 31 T. 32 S. R. 4 W.)

Found - Doug. Fir (now 24" diam.) S. 60° W. 11.2 ft. Scribing visible on partly exposed face "R 5 W"-tree alive & in good condition.

Doug. Fir (now 23" diam.) N. 62° W. 13.2 ft. Previously opened, but nearly healed over-now scribing visible- tree in good condition.

Doug. Fir (now 26" diam.) N. 42° E. 21.8 ft. (not 17.8 ft)- scribing visible on partially exposed face "S31"-tree in good condition.

Partly rotten cedar stump S 58° E. 25.7 ft. Scribing visible "R 4 W T 33 S S 6"

Set - Brass Cap Mkd: "County Surveyor's Office 1964

T 32 S "

R S 36 S R

5 S 1 31 4

W W

T 33 S

Did not mark any new trees.

*Ed. O.K. by:  
L. D. Smith  
MAY 14, 1982  
M 92-34*

133

-----  
C. Corner to Sections 1 & 6. (7.335 R6. 5 & 4)

Found - Rock as described, in mound of rocks.

Fir snag N. 46° E. 15.8 ft. Scribing visible "T 33 SR 4 & 5 W S 1 & 6 BT"

Fir snag S. 77° E. 10.6 ft. Part of face exposed, but no scribing visible.

Doug. Fir (now 15" diam.) S. 39° W. 26.4 ft. Scribing visible on previously opened face. "3 S R 5 W S 1". Tree in good condition. A vertical rock cliff approx. 10 ft. high between this tree & corner.

Set - Brass Cap (on top of bedrock) Mkd: "County Surveyor's Office 1964

T 32 S " Cap not oriented correctly

R S31 R thus - |

5 S 1 S 6 4

W W Erect mound of rocks around pipe.

T 33 S

New BT: 9" Doug. Fir S. 65° E. 25.0 ft. Mkd: "T 33 SR 4 W S 6 CS BT"

Corner lies on very steep, rocky NW slope.

134

Milo E. \_\_\_\_\_, Dep. Surv.  
Wm. Stoffel, Mike Darby, Mike Stone  
June, 1964  
C. S. File No. 53/52