

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

T.H. Mehl, III
Robert Dollar
6/16/67
C.S. File
No. 55/15

140

North $\frac{1}{4}$ Corner of Section 5, T32S, R5W
Found - No trace of Gov't. Brass Cap (1962) at $\frac{1}{4}$ corner.
10" D. Fir S. 83° W. 23 lks., knocked over by logging
12" I. Cedar S. $15\frac{1}{2}^\circ$ E. 35 lks., scribing buried under logs.
Set - $1\frac{1}{2}$ " x 40" Iron Pipe, 32 inches into the ground, from which:
Rescribed - 12" I. Cedar "S RS 749 BT' four feet above ground.

June 16, 1967

141

Sec. Cor. to Secs. 33 & 34, T31-5W. & Secs. 3 & 4, T32-5W.
Found - 20" Fir Windfall, N. $13\frac{1}{4}^\circ$ E. 38.3 ft., shows good scar.
30", now 33" Fir, S. $68\frac{1}{4}^\circ$ E. 48.8 ft., shows good scar.
33", now 35" Fir, N. 66° W. 48.2 ft., shows good scar.
No trace 35" Fir S. 34° W., lies in skid trail.
Found - U.S. Land Office, Brass Cap, properly marked. (1955)
New BT's: 21" D. Fir N. 1° E. 82.4 ft. mkd. T31S R5W S34 CS BT.
30" D. Fir S. 77° W. 46.6 ft. mkd. T32S R5W S4 CS BT.

142

Section Corner to Sections 3 - 4 - 9 - 10.
Found - 1955 Brass Cap at Corner, properly marked.
19" D. Fir, now Snag, S. 72° W. 25.9 ft., scribe visible.
9", now 11" D. Fir, S. 36° E. 7.9 ft., shows scar.
12", now 16" D. Fir, N. 36° W. 46.2 ft., face pitched over.
24" D. Fir, down, N. 74° E. 61.4 ft.
New BT's: 12" D. Fir S. 70° W. 27.9 ft. mkd. T32S R5W S9 CS BT.
10" Maple N. 14° E. 35.6 ft. mkd. T32S R5W S 3 CS BT.

143

$\frac{1}{4}$ Corner to Sections 4 and 9.
Found - Orig. 24", now 36" D. Fir, S. 20° E. 5.4 ft., faint bark
scribe visible, " $\frac{1}{4}$ ".
No trace of N. E. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T32S R 5 W
Office, 1967 S 16 S 15
New BT's: 17" D. Fir N. $81\frac{1}{2}^\circ$ W. 88.4 ft. mkd. $\frac{1}{4}$ S 4 CS BT. $\frac{1}{4}$ S 9
26" Maple S. 42° W. 70.0 ft. mkd. $\frac{1}{4}$ S 9 CS BT.
Note - New logging road bears north 100 ft.

144

Section Corner to Sections 9 - 10 - 15 - 16.
Found - $\frac{3}{4}$ " Iron Pipe at Section Corner, See Ren. #80-B.
50" B.Oak, now 50", S. 52° E. 171.6 ft. Tree has been opened,
"B" visible, face rotting.
7", now 9" W. Oak, S. 22° W. 42.1 ft., shows scar.
12", now 14" W. Oak, N. 69° E. 47.0 ft., shows scar.
No N. W. BT.
New BT's: 14" W. Oak S. 68° E. 40.0 ft. mkd. T32S R5W S15 CS BT.
5" Cedar N. 54° W. 9.7 ft. mkd. S 9 CSBT.
Note - Fence corner lies N. 69° E. 28.0 ft.

145

Section Corner to Sections 15 - 16 - 21 - 22.
Found - Iron Grate at Section Corner, See Ren. #62.
6", now 10" Laurel, N. $29\frac{1}{2}^\circ$ W. 20.7 ft., shows good scar.
10", now 11" B.Oak S. $74\frac{1}{2}^\circ$ W. 47.0 ft., shows good scar.
8", now 8" W.Oak S. $59\frac{1}{4}^\circ$ E. 56.4 ft., scribe visible (CS).
14" Fir, now cut, N. $67\frac{1}{2}^\circ$ E. 41.8 ft., scribe visible (15 CS BT)
Set - Brass Cap alongside I. Grate Mkd: County Surveyor's T32S R5W
Office S 16 S 15
1967 S 21 S 22
New BT's: 7" B.Oak N. 32° E. 15.2 ft. mkd. T32S R5W S15 CS BT.
Note - Corner lies 2.0 ft. west of N. - S. fence line.

146

$\frac{1}{4}$ Corner to Sections 15 and 16. fd. OK 3/92 A. RAMBO M114-78
Found - 18", now 20" B.Oak N. $19\frac{1}{2}^\circ$ W. 96.7 ft., shows good scar.
8" Laurel, now cut, S. $64\frac{1}{2}^\circ$ E. 26.2 ft., scribe visible "CS BT".
5/8" Bolt at $\frac{1}{4}$ Corner, See Ren. #80.
New BT: 14" D. Fir N. $13\frac{1}{2}^\circ$ E. 10.1 ft. mkd. $\frac{1}{4}$ S 15 CS BT.
Note - This corner lies btwn. 2 fences approx. 150.0 ft. E. of
dirt road, running north.

John M. Powell
Frank Jones & Joe Brady
July, 1967
C. S. File No. 53/52

3/92
fd. OK BT
A. RAMBO
M114-78

fd. OK Per
M. Hull
M110-12
4/90

fd. OK Per
M. Hull
M110-12
4/90