

Douglas County Surveyor's Record of
Government Corners Renewed

T 32 T. S. R 5 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

RE-RENEWED SEE CORNER NO. #217 204
C O N T - - New BT - A 13" W. Oak scribed "1/4 S22 CS BT" bears S.77°E.,
88.5 ft. dist.
A 48" culvert bears S.76°E., 35.0 ft. measurement
taken at top center of southerly end said culvert.
Cor. located 32.0 ft. north of R/W fence.

L.E. Monrean
K. Reed - K. Mosely
Doug. Co. Surveyors
Office
April 23, 1980
C.S. 61/6

1/4 Corner for Secs. 15 and 22 205
Found - 1 1/2" iron pipe protruding 0.2 ft. from ground and firmly
set. Originally set by proportionate measurement. Ren. #184
Searched for orig. bearing trees thoroughly, none found.
From Carlile survey, M48-71, a 5/8" iron rod firmly set and
flush with surface of ground bears S.89 1/2°E., 703.5 ft.
(rec. S.88°11'14"E., 706.20 ft.)

from this iron rod,
another 5/8" iron rod firmly set and flush with ground from
Riley survey, C.S. 55/189, bears S.37°W., 2.15 ft. Rec.
distance as per M 48-71, 300.00 ft. from Car axle to 1/4
S15/22, S88°11'14"E.,. We find the dist. to be 278.29 ft.

See attachments to field notes in C.S. 61/6.

New BT's - A 7" Ash bears N.85 1/2°E., 37.9 ft. scribed "1/4 S15 CS BT"
on a double blaze.

An 8" Ash (most westerly trunk of triple trunk tree) bears
S.72 1/2°E., 11.0 ft. (bearing and dist. to center of root
crown of triple trunk). scribed "1/4 S22 CS BT" on a
double blaze.

A 10" Ash (most easterly trunk of triple trunk tree) bears
S.73°W., 36.3 ft. (bearing and dist. taken to center of root
crown of triple trunk) scribed "1/4 S22 CS BT" on a double blaze.

A 12" Ash bears N.29°W., 49.6 ft. scribed "1/4 S 15 CS BT" on
a double blaze.

We tag all trees with DCSO BT tags.

4/80

1/4 Corner for Secs. 22 and 23. 206
Found - A car axle approx. 1 inch in diam. protruding approx. 0.5 ft.
from ground firmly set and from Ren. #97
Possible remains of S.82°W., orig. BT, this is a rotted stump
We find no evidence of blazes or scribing.

From Ren. #97:

An 18" now 29" Cotton wood (Bain) bears S.78°E., 115.5 ft.
(rec. S.81°05'E., 114.7 ft.) healed single blaze, no
scribing visible.

An orig. 16" now 28" W. Oak bears N.60°W., 46.5 ft. (Rec.
N.62°30'W., 46.5 ft.) healed single blaze, no scribing visible.)

We tag trees and mark tags with new bearings and distances as above.

Because record evidence does not tie back to orig. corner WE DO NOT SET
brass cap but only perpetuate 1/4 corner position as determined by
Wenderoth in 1957, C.S. 45/154.

New tags as mentioned in "found accessories". No suitable trees available
in NE and SW quadrants.

4/23/80

1/4 Corner for Secs. 22 and 27. 207
Found - 1 1/4" iron pipe firmly set and protruding 0.8 ft. from ground
from Ren. #87. Pipe is approx 1 ft. west of a random fence
line running east only from 1/4 corner.
Search for but find no evidence of orig. bearing tree.
An 8" now 18" D. Fir bears S.51°W., 18.7 ft. has healed single
blaze. no scribing visible and is tagged with a BLM bearing
tree tag. Ren. #87.
A 10" now a 20" Madrone bears N.52°E., 28.1 ft. (Rec. N.52°25'E.,
29.0 ft.) has partially healed single blaze with scribe
marks visible and is tagged with a BLM bearing tree tag which
is marked S.52°W., 28. ft.

Because of no connection in record to orig. evidence, WE DO NOT SET
a brass cap but only perpetuate the position of 1/4 corner as determined
by Wenderoth in 1956, C.S. 42/88. Iron pipe is still firmly set, we do
not disturb but add a bearing tree as follows:

A 5" Madrone bears N.0°E., 14.0 ft. bark scribed "1/4 S22 CS BT"

No suitable trees available in other quadrants.

5/23/80

T. Plouff - S. Means
April 22-23, 1980
C.S. 61/6
Flause, Deputy, Doug. Co. Surveyors Office