

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 32

T. S.

R 5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Bruce Shaner LS 430
June 9, 1988
C.S. 63/85

227

Section Corner for Sections 11, 12, 13 and 14
Found - 3/4" iron pipe. Ren. #110
16" fir, face overgrown, bears S.51°E., 57.4 ft. (Powell's record 54.0 ft., Ren. #158, but Byron, 1956 shows 57.4 ft.)
18" D. fir, face overgrown, bears N.65°E., 15.0 ft.
14" W. oak, face rotted out, bears N.35 3/4°W., 8.6 ft. (as per record by Frear, County Surveyor, 1920)
Set - Set 2 1/2" brass cap mounted on a 2" x 30" galv. iron pipe, 24" in the ground, in place of 3/4" iron pipe. Cap mkd. "T32S R5W W.M. S11 | S12 1988 RLS 430"
S14 | S13
Reset 3/4" iron pipe alongside brass cap.

Douglas County Surveyors Office
Randall Smith
Stephen Flause
April 20, 1989
C.S. 62/63

228

1/4 Corner for Sections 26 and 27
Found - 1975 County 2 1/2" dia. brass cap on a 1 1/4" O.D. iron pipe protruding 2" above ground. Ren. #191
A 1" I.D. iron pipe protruding 10" above ground bears South 0.5 ft from DCSO BC/IP. Ren. #15
5" now 29" dia. P.pine with a partially healed single blaze, no scribing visible bears N.30°W., 60.1 ft. (agrees with re.) Orig.
14" now 30" D. fir with a fully healed double blaze bears North 44.9 ft. (agrees with record) Per GLO 1901 resurvey.
New BTs - 6" D. fir double blazed and scribed "1/4 S26 CS BT" bears S.36 1/2°E., 13.7 ft.
15" D. fir double blazed and scribed "1/4 S27 CS BT" bears S.19 1/2°W., 19.0 ft.

James Artman
L.S. # 2268
For : Medford Corp.
M 109 - 66
3-16-90

FP 5/8" I.R.
R. Brown 7/92
M117-58

4/20/89
229

1/4 Corner for section 13, T32-5, and section 18 T32-4.
Found - 18" D. fir bears N 51°W., 43.0 ft., healed face
16" D. fir stump bears N69°W., 28.0 ft., scribes visible
Set - 5/8" x 30" iron rod with vap marked " Artman RLS 2268"
New BT's 7" madrone bears N 28°E., 10.5 ft., scribed "1/4 S18 BT"
7" D. fir bears N 74°W., 8.7 ft., scribed " 1/4 S13 BT"
9" D. fir bears S 89°E., 8.6 ft., scribed " 1/4 S18 BT"
1" iron pipe bears N 13°41'07"E., 5.86 ft.

SEE REN #180

Max H. Hull LS #901
For: Gregory
Forest products
April 1990
M 110 - 12
C.S. 63/115

230

1/4 Corner for Sections 10 and 15
Found - A B. Oak, 18" dia. S.32°W., 11.3 ft. blaze healed. Ren. #86
A B. Oak 20" dia. N.57°40'E., 70.2 ft. blaze healed. Ren. No. 86
Set - 5/8" x 30" iron rod with yellow plastic cap mkd. "HULL RS 901"
New BTs - 28" S. Pine, N.50°W., 19.3 ft. scribed.
12" Cedar S.25°E., 8.5 ft. scribed.

4/27/90

Douglas County Surveyors Office
Randall Smith and
Stephen Flause
C.S. File 64/23
January 7, 1992

231

Township Corner - NW Corner Section 6
Found - 1966 Oreg. State Board of Forestry 3" brass cap on a 1 1/2" O.D. Iron pipe protruding 7" above ground. Ren. No. 139
1" O.D. Iron pipe protrudes 5" above ground. Ren. No. 126
1" I.P. bears West, 13.3 ft. from OSBF BC/IP. (agrees w/rec)
55" now 58" dia. D.Fir with a fully healed single blaze on the NW trunk and bark scribed "LS 359" on North trunk bears S.15°W., 13.8 ft. (Rec. S.15°W., 11.5 ft. dist. to bark scribing) Ren. No. 139
4" now 9" dia. 1 1/2 ft. high Hemlock stump with a fully healed blaze, bears S.58°E., 28.3 ft. (agrees w/rec) Ren. No. 139
4" now 11" dia. D.Fir with a fully healed single blaze, bears N.9°E., 19.0 ft. (agrees w/rec) Ren. No. 139
6" now 12" dia. 1 1/2 ft. high D.Fir stump with a fully healed single blaze, bears N.86°W., 54.5 ft. (agrees w/rec) Ren. No. 139
New BTS - (Go to corner position as determined by OSBF in Ren. No. 139)
8" dia. Hemlock double blazed and scribed "T31S R6W S36 CS BT" bears N.43°W., 12.1 ft.
7" dia. Hemlock double blazed and scribed "T31S R5W S31 CS BT" bears N.75°E., 16.6 ft.
Corner lies on a steep North facing slope. (See C.S. File 49/92 for correspondance on the establishment of corner position.)

1/7/92