

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 6 R. W. W. M.

Renewed Corner
Jeanne Richardson
C. J. Wenderoth
Feb. 1942

J. W. Cole
N. E. Richardson
July 1923
Ren. Co. Vol. 1
Pg. 1

F. Briggs
Surveyor
Joseph Jacques
Nov. 18, 1873
Field Book
97.

G. J. Wenderoth
Surveyor

Geo. J. Wenderoth
Reg. Land Surveyor #5.
August 1945.

✓ SOUTH 1/4 SEC. 32 T. 32 S. R. 6 W.
28" Fir N. 24° 12' W. 31.8 feet New O. B. T. 20' Fir Stump N.
21" B. 7.5 feet 1" x 30" Galv. Iron Pipe.

RE-RENEWED, SEE CORNER NO. 29+15

1

✓ 1/4 COR. BET SEC'S 32-33 T. 32 S. R. 6 W. SAME AS # 21
I renewed this corner from the burned out stump of Old Bearing
tree N. 83° W. 353 lks. also hole where other bearing tree had
stood bears N. 40° E. 170 lks. also fences corner at the place
located from trees. I set a 1 1/2 x 24 Galv. pipe and erected
mound of rock around it. Marked two points of ledge rock for
bearing objects N. 45° W. 11.2 ft. and N. 21° 30' E. 40.8 ft.

2

✓ CORNER TO SECS. 27-28-33-34 T. 32 R. 6 W.
I renewed this corner by setting a 1 1/2" x 30" steel bar at the poi
point where an old yew wood post stood. All bearing trees had
been cut but stump remained. SAME AS # 22

3

✓ 1/4 SECTION CORNER BETWEEN SECTIONS 26 & 35
RE-RENEWED, SEE CORNER NO. 30
Set a post for corner. The old tree called for pine
Marked 2 new trees as follows;
White Oak 10 inches Diam. Bears S. 62° W. 237 lks. di
White Oak 8 inches Diam. bears N. 30° W. 445 Lks. dt.

4

✓ 1/4 Sec. Corner between Secs. 13 & 24
RE-RENEWED, SEE CORNER NO. 61
Set 1 1/2" Iron Pipe for corner
Cedar 12" bears S. 60° 35' E. 54.05 feet
" 10" " N. 52° 20' E. 39.25 feet

5

✓ Cor. of Secs. 13-24-18 & 19 (R 5 & R 6 W)
Set 3/4" Iron Pipe
Cedar 36" bears S. 11° 22' W. 44.2 feet RE-RENEWED # 93A
" 16" " N. 69° 15' E. 54.9 feet

6

✓ Cor. of Secs. 13-14-23 & 24
Set 1" Iron Pipe
Chinquipin dead N. 55° W. 38.94 feet
Laurel stump S. 79° 16' W. 15.18 feet
No new trees available Vol. 1 Pg. 172 - Nov. 1929

7

✓ Cor. of Secs. 31-30-36-25. (R 6 & R 7 W)
Set 3/4" Iron Pipe.
Found the 4 original witness trees
4" Fir S. 57° W. 25.74 Ft. dead and scribe rotted away.
30" Fir N. 24° W. 11.22 Ft. Scribe marks very plain.
40" Fir N. 51° E. 11.22 Ft. Scribe marks badly burnt.
30" Fir S. 52° E. 9.24 Ft. Tree lying on ground.
Marked the following new bearing trees.
12" Fir S. 64° 08' W. 38.0 Ft.
8" Alder S. 64° 30' E. 84.9 Ft.

8

✓ 1/4 Cor. between 28 - 33.
Drove Railroad Spike in root of 18" Fir tree.
Found both original witness trees but both badly rotted.
Marked the following new trees.
30" B. Oak S. 42° 41' W. 39.3 ft.
20" W. Oak S. 52° 15' W. 52.35 ft.

9

RE-RENEWED, SEE CORNER NO. 109