

Douglas County Surveyor's Record of  
Government Corners Renewed

32 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21881

54  
 $\frac{1}{4}$  Section Corner between Sec. 1, T32S R6W, & Sec. 36, T31S R6W.  
 Found - Remains of 14" Madrone N.58°E. 9.9 ft.  
 Old Live Oak Stump S.53°W. 3.3 ft., no scribe marks.  
 Top of Ridge 297 ft. West on old blazed line.  
 From all indications corner is right.  
 Set 3" Live Oak Stake for Corner.  
 Scribe - 8" Live Oak N.5°16'W. 31.1 ft.  
 12" Live Oak N.63°56'W. 17.3 ft.

George Wenderoth, Deputy  
 For C. & D. Lumber Co.  
 April 11, 1959  
 C. S. File No. 49/92

54-A  
 $\frac{1}{4}$  Section Corner between Sec. 1, T32S R6W, & Sec. 6, T32S, R5W.  
 Found - 22" Fir West 13.2 ft.  
 Scribed - 24" Fir S.12°18'E. 18.2 ft.  
 14" Fir N.42°40'E. 20.1 ft.  
 Set  $\frac{3}{4}$ " Iron Pipe for Corner.

55  
 $\frac{1}{4}$  Section Corner to Sections 3 & 10.  
 Found - Orig. 36", now 40" Fir Snag S.25°W. 29.7 ft., I  
 open & find good scribing "BT".  
 Now 48" Fir Snag that checks bearing & distance for  
 Original N.W. BT., I open but do not find scribing,  
 may have been bark scribed. This area burned, 1958.  
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959  
 $\frac{1}{4}$  S 3 T32S R6W  
 S10  
 Note - Find  $\frac{3}{4}$ " Iron Rod bears N.45°E. 3.9 ft. from  $\frac{1}{4}$  Cor.  
 New BT's: 32" R. Fir bears S.44°E. 33.6 ft. scribed  $\frac{1}{4}$  S10 CS BT.  
 14" Cedar bears N.85°E. 71.3 ft. scribed  $\frac{1}{4}$  S 3 CS BT.

James W. Byron, Deputy  
 S. A. Blouw  
 June 4, 1959  
 C. S. File No. 49/91

Fd. by  
 SMITH, L.D.  
 4/27/83  
 M 94-19

C.S. 54/53 - J.M.P.  
 9-18-67

TREES CUT. BRASS CAP IN PLACE - NO TREES AT ALL TO SCRIBE - TAGGED STUMPS - REBORN

56  
 Section Corner to Sections 2, 3, 10, & 11.  
 Found - All Original BT's:  
 Orig. 24", now 20" rotted Stump N.35°E. 12.5 ft., shows  
 old scar.  
 18", now 24" Fir Snag, shows good scribing "S 3 R".  
 Orig. 20", now 40" Fir S.60°W. 5.9 ft., shows good  
 scars, I do not open.  
 Orig. 16", now 40" Fir S.65°E. 18.5 ft., shows good  
 scars, I do not open.  
 Set Brass Cap Mkd:  $\frac{S 3}{S10} | \frac{S 2}{S11}$  T32S R6W County Surveyor's  
 Office, 1959  
 New BT's: 18" R. Fir bears N.58°W. 24.6 ft. scribed S 3 T2  
 T32S R6W CS BT.  
 18" R. Fir bears N.37°E. 88.6 ft. scribed S 2  
 T32 S R6W CS BT.  
 22" R. Fir bears S.28°E. 60.6 ft. scribed S11  
 T32S R6W CS BT.  
 25" R. Fir bears West 33.8 ft. scribed S10  
 T32S R6W CS BT.

James W. Byron, Deputy County Surveyor  
 Milo Godfrey  
 S. A. Blouw  
 June 9, 1959  
 C. S. File No. 49/91

57  
 $\frac{1}{4}$  Section Corner to Sections 10 & 11.  
 Found - Both Orig. BT's: Orig. 18", now 24" Fir, partly  
 rotted Snag S.70°E. 18.6 ft., shows good Scribing " $\frac{1}{4}$ S"  
 Orig. 48", now 50" Fir Stump N.10°W. 20.5 ft. I do  
 not find any scribing, may have been bark scribed.  
 Also find  $\frac{3}{4}$ " Iron Pipe at Corner.  
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959  
 $\frac{1}{4}$  S10/S11 T32S R6W  
 New BT's: 16" Cedar bears S.53°E. 38.0 ft. scribed  $\frac{1}{4}$  S11 CS BT.  
 12" R. Fir bears S.85°W. 27.6 ft. scribed  $\frac{1}{4}$  S10 CS BT.

Fd. by  
 SMITH, L.D.  
 4/27/83  
 M 94-19  
 2/85  
 O. FREDERICK  
 M 94-67