

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

9186 - F.D. OK PER M 102-59 94
BY BENTZ

1/4 Corner for Sec. 25, T32-6W. & Sec. 30, T32-5W.
Found - 1" Iron Pipe in North-South fence line. (See signed statement
by Chet Smith, Jr., C.S. 53/52)
7" Ash N. 65 1/2° W. 134.8 ft., found stob believed to be
this tree.

No trace of S.W. BT.

New BT's: 9" Ash(?) South 55.4 ft. mkd: 1/4 S30 CS BT.
8" Ash N. 74° E. 138.0 ft. mkd. 1/4 S25 CS BT.

Note - This corner lies in N-S fence line 220.0 ft. N. of R/W fence.
Location tag on R/W fence line.

Sept. 8, 1967

95

Wit. Corner to 1/4 Corner to Sections 4 and 9.
Found - Orig. 14", now 23" Hemlock, N. 10° W. 24.4 ft., faint
bark scribe "BT".

No trace of Dogwood or Alder Corner Tree.

As this corner now falls in edge of creek, I renew as follows:

Set Brass Cap at Cor. Mkd: County Surveyors T 32 S R 6 W
Office W. C. 15.0 ft. East to
1967 1/4 S 4
S 9

New BT's: 22" Cedar N. 29 1/2° E. 8.5 ft. mkd. W. C. 1/4 S 4 CS BT.
11" W. Fir S. 6 1/2° W. 7.0 ft. mkd. W. C. 1/4 S 9 CS BT.

FD. OK 2/85
O. FROEDERICK
M 92-67 C.S. 63/11

96

1/4 Corner to Sections 8 and 17.
Found - Orig. 20", now 33" Fir, S. 40° W. 9.9 ft., bark scribe visible.
Orig. 24" Fir, now hollow rotten stump, N. 50° E. 29.0 ft.
(Record 27')

Set - Brass Cap at Cor. Mkd: County Surveyors T 32 S R 6 W
Office 1/4 S 8
1967 S 17

Reblazed & Rescribed: 33" D. Fir S. 40° W. 6.6 ft. (from face)
scribed "1/4 S17 CS BT.

New BT: 20" D. Fir N. 44° W. 42.0 ft. mkd. 1/4 S 8 CS BT.

John M. Powell
Frankline Jones & J. Brady
September, 1967
C. S. File No. 54/31

97

1/4 Corner to Sections 3 and 4.
Found - Orig. 36", now 42" D. Fir, N. 70° W. 16.5 ft., faint bark scribe visible.
Orig. 16" D. Fir, now rotten stump, S. 82° E. 5.9 ft.

Set - Brass Cap at Cor. Mkd: County Surveyors T 32 S R 6 W
Office, 1967 1/4 S 4 | S 3

New BT's: 12" D. Fir N. 31° W. 16.7 ft. mkd. 1/4 S 4 CS BT.
8" Yewwood S. 34° E. 23.7 ft. mkd. 1/4 S 3 CS BT.

FD. OK 2/85
O. FROEDERICK
M 92-67 C.S. 63/11

98

Section Corner to Sections 3 - 4 - 9 - 10.
Found - Orig. 36" D. Fir, now 48" Stump, S. 66° E. 31.0 ft., bark scribe visible.
Orig. 50", now 52", bark scribe visible, "T R6".

Iron Rod at Sec. Corner, See Ren. #90A.

8" Tan Oak N. 27° E. 15.4 ft. mkd. S3 R4186 BT.

10" Cedar Stob S. 57° E. (found to be S. 7° W.) 66.5 ft. scribed R4186.

Set - Brass Cap at Sec. Cor. Mkd: County Surveyors T32S R6W
Office S 4 | S 3
1967 S 9 | S 10

New BT's: 6" Chinq. N. 17° W. 20.8 ft. mkd. T32S R6W S 4 CS BT.
12" Laurel S. 10° W. 72.8 ft. mkd. T32S R6W S 9 CS BT.

Note - This corner lies in cut over area approx. 460.0 ft. W. of ridge
top, running about N. - S.

John M. Powell
F. Jones & J. Brady
Sept., 1967
C. S. File No. 54/53

FND. BLM B.C. OK 1-91
M 111-34

99

1/4 Corner to Sections 28 and 27.

Found - 1" Iron Pipe at 1/4 corner, See Ren. #18.

14" Laurel, now 16", S. 23° E. 53.0 ft., scribe visible.

28" W. Oak, now dead, S. 87° W. 58.0 ft., scribe visible.

New BT: 6" D. Fir N. 69° W. scribed 1/4 S 28 CS BT.

Note - This corner lies on east slope of small ridge, top of said
ridge bears west 60.0 ft.