

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T.S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

136

Gary Langlitz  
P. Earle  
C.S. 56/49  
4/23/74

South 1/16 Secs. 26 and 25  
Found - 1" Iron pipe as noted on Wenderoth survey  
M 7 - 19. Also Verified measurements to  
following BT's:  
8" now 10" B.Oak, bears N.44°41'W., 34.0 ft.  
well healed.  
10" now 12" Madrone, bears S.32°10'W., 33.0 ft. partially  
healed.  
Corner lies 13 ft. east of an old N-S fence.

Gary L. Langlitz, County Surveyor Office

fd B.C. 8/90  
M110-48

P. Earle  
C.S. 56/51  
6/11/74

1/4 Corner for Secs. 25 and 36 <sup>9/86 - F.O.K. PER DONBEITZ, M102-39</sup> 137  
Found - 5/8" I.Rod set by Oregon State Hwy Dept. (Refer to State Hwy.  
map drawing No. 8B-30-21 filed in the County Surveyors office  
as State Hwy map J-9, Azalea to Josephine Co. Line Section of  
the New Pacific Highway, Interstate 5)  
To verify the location of this corner we measure the distance between the  
1/4 cor. I. R. and a found iron rod and alum. survey cap at the right-  
of-way station 399+00 244 ft. right of centerline. We find the dist. to  
be 408.79 ft., measured stadiametrically as compared to 409.02 ft.  
computed from the above mentioned map. There is no remaining evidence of  
the original bearing trees.  
At the corner point we set a brass cap buried 5" below ground surface, mkd:  
COUNTY SURVEYORS T 32 S  
OFFICE S 25 1/4  
1974 S 36  
R 6 W

Reset iron rod alongside and mark the following BT's:  
a 16" Incense cedar bears N.71 1/2°W., 148.9 ft. scribed "1/4"  
S25 CS BT". This tree stands approx. 6 ft. westerly of the  
westerly R/W fence along Interstate 5 Freeway.  
A 11" Ponderosa Pine, bears S.36°W., 103.5 ft. scribed "1/4"  
S36 CS BT". This tree stands in the median strip between the  
north and southbound lanes of Interstate 5.  
Note: This corner lies at the easterly edge of the gravel shoulder along  
southbound lanes of I-5.

6/11/74

138

1/4 Corner for Secs. 8 and 9.  
Found - Orig. 36" Fir, bears S.70°E., 25 lks. dist. now 24" x 5 ft. high  
rotted stub, knocked downhill by windfall.  
Orig. 40" Fir, bears N.60°W., 39 lks. now 46" burnt stump in  
place axe work on face visible bark scribes eroded away.  
Original laurel post missing.  
Set - 1 1/2"x36" Galv. I.P. with 3" bronze cap mkd. "OREGON STATE  
BOARD OF FORESTRY 1/4 S8 S9 1974 RS 359", 34" in ground in  
mound of rock, and from which a:  
46" Orig. Fir (stump) bears N.60°W., 25.7 ft. to face; bark  
scribed 1/4 S8 BT.  
23" Fir, bears N.5 1/2°E., 53.9 ft. to face; scribed 1/4 S9  
BT RS 359.  
Set - 4"x4"x72" white painted cedar post N.76°W., 10.2 ft. from corner  
pipe. Oregon State Forestry Dept. metal location poster on 23"  
Fir BT. N.5 1/2°E., 53.9 ft.

10/8/74

Arnold G. Gibson  
State Dept. of Forestry  
10/8/74  
C.S/ 58/18

1/4 Corner for 5 and 4. 139  
Found - An orig. 30" now 44" D.Fir bearing N.30°E., 17.2 ft.  
We find a faint "BT" scribed in the bark. Also a "1/4"  
chopped in the bark but it is not an orig. marking.  
An orig. 20" now 34" D.Fir bearing N.15°W., 22.4 ft. We  
find faint bark scribing "1/4 BT".  
At the corner point we set a 1"x30" I.P. with brass cpp attached:  
COUNTY SURVEYORS T 32 S  
OFFICE S 5 S 4  
1974 1/4  
R 6 W  
New BT's: 30" D.Fir bears S.53°W., 33.5 ft. scribed "1/4 S5 CS BT".  
12" Yew bears S.74°E., 36.2 ft. scribed "1/4 S4 CS BT".  
Compass declination setting: 20° East

11/5/74

Gary Langlitz  
P. Earle  
Office  
11/5/74  
C.S. 57/12