

Douglas County Surveyor's Record of
Government Corners Renewed

T 32 T. S. R 6 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21891

161

C O N T. - - -

Stephen Flause, Deputy
Douglas Co. Surveyor
T. Plouff
Karen Mosely
April 6, 1981
C.S. 61/19

Set - The location of the cedar post remains in the ground which agrees with the record bearing and distance from the orig. southeast bearing tree is referenced out, the post remains are removed and a DCSO 2 1/2" brass cap on a 1" x 30" iron pipe is placed in the referenced location. Cap monument firmly set & protrudes 5" from ground & mkd. DOUGLAS COUNTY SURVEYOR
T32S S29 S28 S32 S33 R6W 1981
New BT's- A 10" DBH D. fir bears N.51 1/2°E., 26.0 ft. Tree is scribed T32S R6W S28 CS BT on a double blaze.
A 6" DBH W. fir bears S.32°W., 29.6 ft. Tree is scribed T32S R6W S32 CS BT on a double blaze.
An 11" DBH D. fir bears N.03°W., 28.6 ft. Tree is scribed T32S R6W S29 CS BT on a double blaze.
All bearing trees are tagged with DCSO BT tags.

4/6/81

162

Center South 1/16 Corner Section 30

Found - 1" x 30" Iron pipe with brass cap attached properly mkd., bent up and lying out of position due to cat work. M 39 - 23
13" now 14" cedar with scribed "CS 1/16 S30 CS BT" in partially healed double blaze.
10" now 12" madrone with well healed double blaze.
Set - I reset found brass cap using record bearings & distances from both found BTs as follows:
14" cedar bears S.51°E., 72.5 ft.
12" madrone bears N.68°W., 34.8 ft.
I add marks "Reset 1982" to brass cap.

12/30/82

163

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
John Powell - Randy
Smith
December 30, 1982
C.S. 62/1

Center 1/4 Section Corner of Sec. 10.

Set - Oregon State Department of Forestry 1-1/2" x 36" aluminum pipe with aluminum cap with magnetic insert, 34" in the ground.
New BTs- 18" fir bears N.54-1/2°W., 10.6-ft.
6" fir bears N.77-1/2°E., 6.2-ft.
note- 4" x 4" x 72" white painted cedar post bears S.61°E., 1.8-ft.

4/27/83

164

Lloyd D. Smith
L.S. #1101
For: Oregon State
Dept. of Forestry
April 27, 1983
M 94 - 19

1/4 Corner for Sec. 2; and Sec. 35 of T.31-6

After a diligent search, I did not find any definite evidence of the corner position or bearing trees, except a Roseburg Lumber Co. location poster circa 1961, which reads "people seem to think this 1/4 S - can't find scribe marks", posted on a stump. I cut into said stump which had the lower portion of a face with no definite scribing or axe work but fit proper diameter and direction for SW BT.

Set - I then set a 5/8" x 30" rebar for the corner with properly marked alum. cap at proportionate distance between adjacent section corners. Aforementioned stump fit position within 5 feet.

New BTs - 6" fir bears S.49°45'W., 24.03 ft. mkd. 1/4 S2 LS 1987 BT.
7" fir bears N.40°W., 19.14 ft. mkd. 1/4 S35 LS 1987 BT.

Corner lies on gentle southerly slope approx. 120 ft. southerly of Rd. #31-6-35.

165

Orrin K. Frederick
L.S. #1987
For: Boise Cascade
Timberlands of Ore.
Febr. 21, 1985
M 90 - 67
C.S. 63/11

1/4 Corner for Sections 2 and 3.

Found - a 1967 County brass cap monument loosely set and leaning easterly. Ren. #108

I RESET the monument, exposed 15", in a mound of stone at the corner point from which:

30" fir bears N.80°W., 13.2 ft. lower blaze opened, "B" visible.
33" fir bears East 21.8 ft. with healed blaze.

New BT - 9" hemlock bears S.15°E., 52.14 ft. to center mkd. 1/4 S2 LS 1987 BT.

166

Section corner for Secs. 2, 3, 10 and 11

Found - 1959 County brass cap monument firmly set, exposed 14". Ren. #56

From which: 45" fir bears S.65°E., 18.5 ft. healed blaze.

40" fir stump bears S.60°W., 6.0 ft. with healed blaze.

20" fir snag bears N.37°E., 88.5 ft. with healed blaze.

26" fir bears S.28°E., 60.7 ft. with scribing visible.