

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

41

Section Corner to Sections 1 - 2 - 11 - 12
Found - Orig. 30", now 36" Fir, N. 5° E. 7.9 ft., bark scribed.
Orig. 24", now 36" Fir, S. 50° E. 40.3 ft., bark scribed.
Orig. 30", now 34" Fir, S. 20° W. 66.0 ft., bark scribed.
Orig. 30", now 36" Fir, N. 40° W. 5.9 ft., faint scribe marks visible.
1" Iron Pipe at Section Corner. (See Johnstone's Corner M 33 - 49)
New BT's: 9" D. Fir N. 50° E. 11.6 ft. scribed T32S R7W S 1 CSBT.
7" D. Fir S 18° E. 27.2 ft. mkd. T32S R7W S12 CS BT.
9" Laurel S. 35° W. 30.6 ft. mkd. T32SR7W S11 CS BT.
Note - This corner lies about 580.0 ft. west of ridge top. Location tag on top of ridge East of corner. *Fd. O.K. Mar. 1970*

42

1/4 Corner to Sections 1 and 12.
Found - 36", now 32" Fir, N. 45° W. 6.6 ft., bark scribed.
36" Fir, now stob, S. 45° E. 6.6 ft., bark scribed.
1" Iron Pipe at 1/4 Corner. (See Johnstone's Corner, M 33 - 49)
New Bearing Trees: 22" D. Fir S. 27° W. 14.1 ft. mkd. 1/4 S12 CS BT.
Roseburg Lumber BT: 6" D. Fir N. 67° E. 29.5 ft. mkd. 1/4 S 1 BT.
Note - This corner lies 20.0 ft. N. of skid road & 125.0 ft. W. of logging road. E. - W. Line crosses just south of bridge. *Fd. O.K. Mar. 1970*

43

7
Z
N
Sec. Cor. to Secs. 25 & 36, T32-7W. *Fd. O.K.*
and Secs. 30 & 31, T32-6W. *SEE RESURVEY Vol. 42 Pg. 16509*
Found : 3/4" I.P. by Wenderoth, See Ren. #8, T32-6W.
16" Alder S. 64° 30' E. 84.9 ft. by Wenderoth.
Stump of 36" Fir BT N. 24° W. 17 lks.
Bug-killed 48" Fir BT N. 51° E. 17 lks.
Blowdown 40" Fir BT S. 52° E. 14 lks.
4" Fir BT S. 57° W. 39 lks. destroyed by road construction.
12" Fir BT S. 64° 08' W. 39.0 ft., destroyed by road Const.
Set - 1 1/2" x 30" Iron Pipe, 18" into the ground & referenced BT's:
4" Chinkapin N. 40° E. 23.8 ft. scribed "X" (at breast ht.) BT.
7" White Fir S. 78° E. 77.1 ft. scribed S31 RS 749 BT.
5" Ponderosa Pine S. 28 3/4° E. 19.1 ft. scribed S31 RS749 BT.
No BTs. were available in the NW. or SW quads. This is an area of snags, culls and reproduction. After five years when this area is relogged, BT's. can be securely established in these two quads.

MICROFILM TO HERE 10/67

44

1/4 Corner to Sections 15 and 22.
Found - 1 1/2" Iron Pipe, out of ground, pulled when S.E. BT. fell, Ren. #18.
Orig. 50" D. Fir, now 50", N. 75° W. 37.0 ft., bark scribe visible.
Orig. 16" D. Fir, now down, S. 65° E. 5.9 ft.
Reset - 1 1/2" Iron Pipe at 1/4 Corner from N.W. Bearing Tree.
New BT's: 7" Chinquapin S. 76° W. 17.1 ft. mkd. 1/4 S22 CSBT.

45

1/4 Corner to Sections 21 and 22. *Fd. O.K.*
Found - 1 1/2" Iron Pipe, See Ren. #16. *SEE RESURVEY Vol. 42 Pg. 16510*
Orig. 30", now 40" D. Fir, N. 55° E. 20.5 ft., very faint bark scribe.
9", now 13" D. Fir, N. 77 1/2° W. 55.4 ft., shows good scar.
New BT: 10" D. Fir S. 89° E. 42.5 ft. mkd. 1/4 S22 CS BT.

46

1/4 Corner to Sec. 7, T32-7W. and Sec. 12, T32-8W.
Found - Orig. 44" Pine, now 48", S. 4° W. 67.3 ft., reblazed & scribed
"1/4 S12 RS33 BT.
46" Pine, now down & burnt, S. 85° E. 63.4 ft.
Corner hits very good for call of 2 chains - Wooden Post at Corner.
Set - Brass Cap at Cor. Mkd: County Surveyor's R T 32 S R
Office 8 S 12 | S 7 7
W 1967 W
New BT: 6" Pine N. 45° E. 18.6 ft. mkd. 1/4 S7 CS BT.

*Fd. OK
9/189
M108-69
C.S. 6324
M. HULL*

Robert Dollar Co. John M. Powell
By T.H. Mehl, III Frank Jones & Cliff Stone
May 10, 1967 December, 1966 - January, 1967
C.S. File No. 54/36

John M. Powell
Frank Jones & Joe Brady
November 3 & 6, 1967
C. S. File No. 54/36