

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97001

96

East $\frac{1}{4}$ Corner to Section 12.

Set - $\frac{5}{8}$ " Iron Rod and Alum. Cap by proportionate measurement.

Bearing Trees: 12" D. Fir N. $69\frac{3}{4}^\circ$ W. 24.1 ft.
8" D. Fir N. $43\frac{1}{4}^\circ$ E. 9.5 ft.

97

Sec. Cor. To Secs. ~~12 & 13~~, T32-7 and Secs. ~~7 & 18~~, T32-6.

Set - $\frac{5}{8}$ " Iron Rod with Alum. Cap.

Bearing Trees: 10" D. Fir N. 68° E. 7.0 feet
10" D. Fir S. $7\frac{3}{4}^\circ$ E. 37.2 feet.
9" D. Fir S. 45° W. 6.2 feet.
21" D. Fir N. $35\frac{1}{2}^\circ$ W. 27.7 feet.

Ed. O.K. - Mac 1970
JMP

98

$\frac{1}{4}$ Corner to Sections 24 and 25.

Found - Orig. 30", now 40" Fir North 4.0 ft., down, stump in place, "BT" bark scribe.

No trace of Orig. BT. to S.E. due to roadway to creek.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970
T 32 S R 7 W
 $\frac{1}{4}$ S 24
S 25

New BT's: 50" D. Fir S. 5° E. 70.8 ft. mkd: " $\frac{1}{4}$ " S25 CS BT".
30" D. Fir N. 88° W. 9.8 ft. mkd: " $\frac{1}{4}$ " S24 CS BT".

This corner lies under log of a BT. approx. 60 ft. E. of old logging road. Best route to corner, $\frac{1}{4}$ miles from Rober Dollar Logging Road at junction of Totten Creek.

3/11/70

99

Section Corner to Sections 23 - 24 - 25 - 26.

Found - Orig. 10", now 21" Fir, alive, N. 18° E. 11.2 ft., shows good axe scar. We Rescribe: "T32S R7WS24 CS BT".

Orig. 16", now 30" Fir, alive, S. 45° E. 46.9 ft., bark scribe visible, poor. Rescribe "T32S R7W S25 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970
T 32 S R 7 W
S 23 | S 24
S 26 | S 25

New BT: 40" D. Fir N. 22° W. 42.9 ft. mkd: T32S R7W S23 CS BT".

No suitable trees close in Section 26.

This corner lies on very steep, N. E. slope in scattered old growth fir and dense chinquapin and laurel brush.

3/11/70

100

$\frac{1}{4}$ Corner to Sections 14 and 23.

Found - Orig. 14", now 26" Fir, alive, N. 50° E. 14.5 ft., frag. bark scribe and an axe notch below blaze.

Rescribe: " $\frac{1}{4}$ " S14 CS BT".

Orig. 16", now 22" Laurel, alive, S. 60° E. 8.6 ft., prev. opened, blaze decayed. Rescribe: " $\frac{1}{4}$ " S23 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1970
T 32 S R 7 W
 $\frac{1}{4}$ S 14
S 23

New BT: 36" Pine S. 41° W. 28.7 ft. mkd: " $\frac{1}{4}$ " S23 CS BT".

This corner lies 60 ft. north of ridge, sloping westerly.

3/10/70

101

North $\frac{1}{4}$ Corner Section 2, T33-7W.

Set - $\frac{5}{8}$ " Iron Rod and Scribed:

10" Madrone S. 55° W. 26.90 ft.

8" Madrone S. 11° E. 16.10 ft.

Found - 1" I. P. N. 9° 33' W. 17.28 feet.

3/29/71

Howard W. Johnstone
For Rsborg. Lumber
Feb. 1970 M 39 - 14

Vernon R. Tracy
Jack Heritage & V. Perron
March, 1970 C. S. File No. 54/36

MARCH 71

C.E. Masters
For: Corwin
C.S. 55/192
M 41 - 39

Jan. 1972