

Douglas County Surveyor's Record of
Government Corners Renewed

T 32 T. S. R 7 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Mark Smalley
L.S. #2354
For: Roseburg Resources
July 1993
M 117-48

1/4 COR. SECS. 28 & 33 *Ren'd S 79*
Found - 1 1/2" Iron Pipe.
BTs - 34" Fir, N.15°W., 31.7', healed face.
16" Fir, S.22°E., 21.1', rotten stump.
30" Fir, S.38°W., 21.0', healed face.
Scribed -
11" Madrone N.14°E., 25.5', "1/4 S28 BT"
18" Fir, S.79°W., 74.5', "1/4 S33 BT"

129

Mark Smalley
For: Kenneth Ford
July 1994
M 120-43

1/4 Corner Secs. 1; 36 T31-7
Found - 1 1/2" IP (Ren. #90-A)
30" Cedar N.25°E., 34.5', healed.
24" Pine, S.24°E., 28.2', Part. healed.
New BTs- 10" Fir, N.19°W., 13.7', "1/4 S BT"
6" Fir, N.57°E., 18.6', "1/4 S BT"

130

Mark Smalley
Roseburg Forest Prod
CS 63/154
7/12/94

SECTION CORNER TO 1, 2 & 35, 36 OF T31-7
FOUND - 1964 BCIP
BTs - 17" Fir, N.9°W. 21.1', good healed face
36" Fir, N.80°E. 31.7', O.B.T
14" Fir, S.20°E., 7.9', down, O.B.T
16" Fir, S.60°W., 9.9', good healed face, O.B.T
20" Fir, N.17°W., 80.52', good healed face, no rec.
New Accessories -
10" Cedar, S.79°W., 23.3', scribed "S2 BT"
corner is 200' east of 31-7-25.1 road

131

132