

Douglas County Surveyor's Record of
Government Corners Renewed

32 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Robert M. Thompson
Witness: R. Gledhill
Feb. 28, 1961
C. S. File No. 51/181

Renewal of 2 - $\frac{1}{4}$ Corners on Range Line, Secs. 31 & 36, T32S, R8W & R9W. 24

At EAST $\frac{1}{4}$ Corner Section 36/ only,
I find $\frac{3}{4}$ " I. P. with brass cap, from which A:
20" D. Fir bears S.72°W. 67 lks.(O.B.T.), now 30" cut stump)
8" D. Fir bears N.35°W. 33 lks.(O.B.T.), now 12" and down.
To renew I scribe A:
6" D. Fir, S.67°W. 28.4 ft. " $\frac{1}{4}$ " S36 BT". 41
6" D. Fir, North 9.6 ft.
No other trees within reasonable distance.

At WEST $\frac{1}{4}$ Corner Sec./31 only.
I find 1" I.P. with brass cap, from which a: 42
18" D.Fir, now 20", bears N.72°E. 58 lks. (O.B.T.)
12" D.Fir, S.86°E. 74 lks., now 16" cut stump.
To renew I scribe A: 9" D. Fir N.35°E. 18.5 ft. " $\frac{1}{4}$ " S31 BT".

James W.
Byron, Co.
Surv.
Terry Connell
Aug. 27, 1965
C.S.File
No. 49/91

$\frac{1}{4}$ Corner to Sec. 1, 32-8W. & Sec. 6 32-7W. 26
Found - Both Orig. BT's., each checks bearing & distance. 131
Orig.14", now 22" Fir N. 70° W. 6.6 ft., shows good bark
scribing " $\frac{1}{4}$ " S BT".
Orig. 14", now 22" Fir S.55°E. 6.6 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T32S $\frac{1}{4}$ R8W S 1/S 6 R7W
Rescribe now 22" Fir N.70°W. 6.6 ft. " $\frac{1}{4}$ " S 1 CS BT".

John M. Powell
Frank Jones & C. Stone
C. S. File No. 54/36

TOWNSHIP CORNER: T.32S.-Rs. 7 & 8W. & T31S.-Rs. 7 & 8W. 27
Found - 8", now 13" Live Oak, S. 78° E. 40.3 ft., opened for scribe.
12"D. Fir, now rotten stob, N. 45° W. 64.0 ft.
No trace of N. E. nor S. W. Bearing Trees.
Set - Brass Cap at Township Corner Mkd:
County Surveyors Office R8W S 36 | S 31 R7W
1966 S 1 | S 6
T 32 S.
New BT's: 10" D.Fir S. 72° W. 33.6 ft. mkd. T32S R8W S 1 CS BT.
12" D.Fir S. 48 $\frac{1}{2}$ ° E. 24.4 ft.mkd. T32S R7W S 6 CS BT.
8" Live Oak N. 53° E. 46.6 ft. mkd. T31S R8W S31 CS BT.
6" Live Oak N. 48° W. 4.6 ft. mkd. S 36 CS BT.
Note - This corner lies about 33.0 ft. E. of creek on steep, W. slope.
12/1/66

Corner to R9W S 31 | R8 T31S Closing Corner 28
S 1 | S 6 T32S
Found - Brass Cap, 1917, at Corner, but out of the ground.
16", now 28" D. Fir, S. 10° E. 43.6 ft., shows good scar.
30" D. Fir S.10° W. 54.0 ft.(not 46.2 ft.), shows good scar.
60", now 55" D. Fir, N. 14° W. 19.1 ft., shows bark scribing.
Reset - G.L.O. 1917 Brass Cap at Elsinga Corner.
All Bearing Trees tagged and all right.
This corner lies south of Road 50.0 ft. in part of fill. 12/21/66

Sec. Cor. to Sections 4 & 5, T32-8W. & Secs. 32 & 33, T31-8W. 29
Found - Orig. 12", now 15" Laurel N. 35° E. 23.1 ft., opened for scribe,
none, rotted.
Orig. 30" S. Pine, now stump, S. 50° E. 75.0 ft.
Orig. 8", now 10" Laurel S. 40° W. 22.4 ft., opened for scribe,
"W" and other marks not legible.
Orig. 24" Fir gone but found stump hole of N. 25° W. 46.9 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's T31S S 32 | S 33
Office, 1967 T32S R8W S 5 | S 4
New BT's: 18" D. Fir S. 23 $\frac{1}{2}$ ° W. 13.3 ft. mkd. T32S R8W S5 CS BT.
9" Laurel S. 75° E. 29.2 ft. mkd. T32S R8W S4 CS BT.
9" Laurel N. 50° E. 32.4 ft. mkd. T31S R8W S33 CS BT.
12" Laurel North 16.0 ft. mkd. T31S R8W S32 CS BT.
1/6/67