

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

48

$\frac{1}{4}$ Corner to Section 30 only, T32-8W.
Found - G.L.O. Brass Cap, properly marked in 1917.
Orig. 40" D.Fir, now stump, S. 80° E. 12.5 ft., shows good scar.
No trace of N.E. Bearing Tree.
New BT's: 5" Pine N. 30° E. 6.8 ft. mkd. $\frac{1}{4}$ S30 CS BT.
7" Pine S. 2° W. 13.5 ft. mkd. $\frac{1}{4}$ S CS BT.

49

$\frac{1}{4}$ Corner Section 18 only, T32-8W.
Found - G.L.O. Brass Cap, properly marked in 1917.
48" D.Fir, now 52" Stump, N. 71° E. 42.9 ft., opened & shows
good scribe " $\frac{1}{4}$ ".
16" Sugar Pine, now 27" Stump, S. 69° E. 64.0 ft., shows good scar.
New BT's: 5" Tan Oak S. 34° W. 9.6 ft. mkd. S18 CS BT.
48" Sugar Pine N. 30° W. 30.4 ft. mkd. $\frac{1}{4}$ S24 CS BT.
There are no other trees in range 8 to scribe.
Note - This corner lies on the west of a cutting line.

50

$\frac{1}{4}$ Corner to Section 24 only, T32-9W.
Found - G.L.O. Brass Cap, properly marked in 1917.
24", now 30" D. Fir, N. 29° W. 13.9 ft., shows good scar.
6" D.Fir, now out of place due to small slide, S. 60° W. 27.2 ft.,
Almost dead, show scar.
New BT: 8" Yew S. 15° W. 10.2 ft. mkd. $\frac{1}{4}$ S24 CS BT.

51

$\frac{1}{4}$ Corner to Section 12 only, T32-9W.
Found - G.L.O. Brass Cap, properly marked in 1917.
36", now 42" D.Fir, S. 27° W. (Record S.77 $\frac{1}{2}$ °W.) 82.5 ft., shows good
scar.
6", now 10" Laurel, N. 37° W. 52.8 ft., shows good scar.
New BT's: 9" Pine S. 22° W. 27.1 ft. mkd. $\frac{1}{4}$ S7 CS BT.
10" Pine N. 85° W. 18.7 ft. mkd. $\frac{1}{4}$ S7 CS BT.

52

$\frac{1}{4}$ Corner to Section 6 only, T32-8W.
Found - 24", now 30" D. Fir Windfall, S. 62° W. 40.9 ft. (BT. was about
50' down the hill. There was a good stump hole to get the
bearing & dist. from, shows good scribe " $\frac{1}{4}$ ".
Other BT gone.
G.L.O. Brass Cap, properly marked in 1917.
New BT's: 12" Hemlock N. 25° E. 50.6 ft. mkd. $\frac{1}{4}$ S 6 CS BT.
10" Hemlock N. 36° E. 30.6 ft. mkd. $\frac{1}{4}$ S 6 CS BT.
Note - This corner lies 50.0 ft. East of Creek.

53

Corner to Sections 6 and 7 only, T32-8W.
Found - G.L.O. Brass Cap, properly marked in 1917.
18", now 12" Cedar Snag, N. 5° E. 38.3 ft., shows scribing.
10", now 12" D.Fir, S. 69° E. 31.0 ft., shows good scar.
New BT: 6" Tan Oak N. 66° E. 2.0 ft. mkd. T32S R8W S6 CS BT.
Note - This corner lies 15.0 ft. south of creek.

54

$\frac{1}{4}$ Corner to Section 1, T32-9W.
Found - G.L.O. Brass Cap, properly marked in 1917.
24", now 25" Cedar Snag, S. 77° W. 22.4 ft., shows good scribe.
No trace of N. W. BT.
New BT's: 42" D.Fir S. 64° W. 23.5 ft. mkd. $\frac{1}{4}$ S1 CS BT.
36" D.Fir N. 82 $\frac{1}{2}$ ° W. 47.5 ft. mkd. $\frac{1}{4}$ S1 CS BT.
Note - This corner lies 100 ft. west of creek.

John M. Powell
Frank Jones & Joe Brady
July, 1967
C. S. File No. 54/44