

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 32 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORG. 21881

John M. Powell
Frank Jones & W. Penley
April, 1968
C. S. File No. 54/65

Section Corner to Sections 17 - 18 - 19 - 20. 70
Found - Orig. 12", now 22" S.Pine, N.60°E. 19.8 ft., tree opened,
scribe visible.

No trace of other BTs. Small Laurels & L.Oak.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1968

T 32 S	R 8 W
S 18	S 17
S 19	S 20

New BT's: 8" Laurel S.32°E. 21.8 ft. mkd. T32S R8W S20 CS BT.
7" D.Fir S. 4°W. 15.9 ft. mkd. T32S R8W S19 CS BT.
36" D.Fir N.53°W. 53.5 ft. mkd. T32S R8W S18 CS BT.
22" S.Pine N.60°E. 19.8 ft., O.K. and Tagged.

$\frac{1}{2}$ Corner to Sections 23 and 24. 71
Found - 8", now 26" D.Fir, S.62°W. 64.0 ft., opened for scribe "1/1"
No trace of N.E. BT.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1968

T 32 S	R 8 W
S 23	S 24

New BT's: 16" D.Fir N.76°W. 39.2 ft. mkd. $\frac{1}{4}$ S23 CS BT.
12" D.Fir S.51°E. 30.0 ft. mkd. $\frac{1}{4}$ S24 CS BT.

Section Corner to Sections 23 - 24 - 25 - 26. 72
Found - 40", now 52" D.Fir, N.50°E. 19.8 ft., shows bark scribing.
40" D.Fir, now 26" Stob, S.30°E. 21.1 ft., shows no scribing.
No trace of SW & NW BT's.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office 1968

T 32 S	R 8 W
S 23	S 24
S 26	S 25

Rescribed BT: 52" D.Fir N.50°E. 19.8 ft. mkd. T32S R8W S24 CS BT.
New BT's: 10" D.Fir S.26°W. 45.0 ft. mkd. T32S R8W S26 CS BT.
24" D.Fir S.85°E. 47.8 ft. mkd. T32S R8W S25 CS BT.
No trees available to N.W.

Note - Creek is 360.0 ft. north of this corner.

Section Corner to Sections 13 - 14 - 23 - 24. 73
Found - Orig. 40", now 60" D.Fir, S.89°W. 19.1 ft., bark scribe
visible, "T32S R8W S23, faint BT".
Orig. 10" Laurel, now dead, N.70°E. 26.4 ft., rotted out.
No trace of S.E. or N.W. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1968

T 32 S	R 8 W
S 14	S 13
S 23	S 24

New BT's: 10" Laurel N.36°W. 33.6 ft. mkd. T32S R8W S14 CS BT.
16" Tan Oak S.12°W. 14.9 ft. mkd. T32S R8W S23 CS BT.
48" D.Fir S.71°E. ^{41.4 ft.} mkd. T32S R8W S24 CS BT.
No good trees reasonable to N.E.

$\frac{1}{2}$ Corner to Section 14 and 15. 74
Found - Orig. 24", now 33" D.Fir, S.83°W. 21.8 ft., bark scribe visible.
Orig. 10", now 21" D.Fir, S.30°E. 11.9 ft.

20x12x10 Stone, approx. size, marks visible, " $\frac{1}{4}$ ".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1968

T 32 S	R 8 W
S 15	S 14

Reblzd.&Rescrd: 33" D.Fir S.83°W. 21.8 ft. mkd. $\frac{1}{4}$ S15 CS BT.
21" D.Fir S.30°E. 11.9 ft. mkd. $\frac{1}{4}$ S14 CS BT.

Note - Corner lies approx. 33.0 ft. S. of creek, running N.W.

$\frac{1}{4}$ Corner to Section 27 and 34. *See 2007 BLM Resurvey* 75
Found - 12" Laurel, burnt out, N.65°W. 11.2 ft., "BT" visible, very old,
doubt if orig., very old cruiser's marks.
9" Laurel, burnt out, S.22°E. 21.1 ft., very old " $\frac{1}{4}$ S" on same, not
scribe work. This mark probably 15-20 years old.
Having found bearings & distances to be of record & such old evidence, I
renew: (Checked call to creek by pacing 396 ft., very steep, checked fair)

(continued over)