

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Brandt,  
R. A.  
C.S. File  
No. 55/129

Section Corner to Sections 19 - 20 - 29 - 30.  
Found - 12" S. P. S. 18 1/2° E. 32.1 ft.  
7" Madrone S. 27° W. 27.8 ft. ) See Ren. #22.  
8" D. Fir N. 41° 21' W. 13.2 ft. )  
5" Tan Oak, broken off.  
Set - 7/8" Hex. Drill Steel, See Renewal No. 22.  
Scribed - 4" Chinquapin N. 52° E. 11.9 ft. mkd: T32S R8W S20 RS41 BT.

105

Oct. '69

John Powell & Crew  
C.S. File 54/65

1/4 Corner to Sections 3 and 10.  
Found - 20" D. Fir Corner Tree, now down, faint bark scribe "S /"  
Orig. 10" D. Fir, now stob, N.30°E. 6.6 ft., faint bark scribe "BT".  
Orig. 24" D. Fir, now stump, S.40°E. 13.9 ft., no scribe visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 32 S R 8 W  
Office S 3  
1970 S 10

106

New BT's: 30" D. Fir N.78°E. 13.0 ft. scribe visible "1/4 S 3 CS BT".  
4" D. Fir S.69°W. 15.8 ft. scribed "CS BT. F D O K D. Edwards  
No other trees available to the south. 8/2005 4148-31  
This corner lies approx. 300 ft. east of ravine.

3/26/70

107

A. Vict , Doug. Co.  
Jim Cook, Karen Cheney  
Aug. 31, 1976  
C.S. 59/18

Section Corner For Secs. 30, 29, 31 and 32.  
Found - A 1968 Brass cap uprooted in root wad. Entire area has slid and  
all but the 1968 Fir, 24", S.56 1/2°W., 62.9 ft. now 32" Dia.)  
are down. Found no trace of 24" Pine. Ren. #90  
Set - A witness corner that bears N.37°W., 89.3 ft. with a brass cap  
stamped: Douglas Co. Surveyor 1976  
Witness Corner

RE-RENEWED, SEE CORNER NO. #121

S 30 | S 29  
S 31 | S 32  
T 32 S R 8 W  
S 37° E 89.3  
New BT's - A 10" D. Fir, bears S.2°W., 15.4 ft. mkd. "X" and "BT" in a  
double blaze.  
An 11" Chinquapin, bears N.2°W., 41.0 ft. mkd. "X" and "BT"  
in a double blaze.

8/31/76

108

Howard W. Johnstone  
For: Roseburg Lmbr.  
Co.  
April 1980  
M 83 = 25

Center 1/4 Corner for Section 1  
Set- 5/8" x 30" Iron Rod and Alum. Cap  
BT's- 16" Cedar bears S.2°E., 22.8 ft.  
7" Cedar bears N.54°W., 31.0 ft.

Howard Johnstone  
For: Rsb. Lmbr.  
Co.  
April 1980 M 83-26

Center 1/4 Corner for Section 2  
Set- 5/8" x 30" Iron Rod and Alum. Cap  
BT's- 8" Fir bears N.87°W., 35.0 ft.  
8" Fir bears S.20°E., 31.0 ft.

109

110

Job M. Powell  
Doug. Co. Surveyors  
Office.  
Witness: Randy Smith  
March 16, 1982  
C.S. 61/30

1/4 Corner for Sections 20 and 29  
Found - 5/8" iron rod set by Gordon Caster, BLM Cadastral Surveyor.  
Note: "In a phone conversation between myself and Gordon Caster (BLM  
Surveyor from Medford Dist.), I was told that the 5/8" I.R. was set at midpoint  
on the section line in conjunction with an administrative survey and that it  
is not an official cor." (signed) Gregory Quibell, Douglas Co. Surveyors Off.  
Found - 7" D. fir bears S.89°W., 26.0 ft., tagged not scribed.  
10" Madrone bears N.36°E., 15.2 ft., tagged not scribed.  
Note: "As in 1968, I found no evidence of orig. corner". (signed) John  
M. Powell.  
New Accessories:  
PK nail in 11" Madrone bears S.34°E., 68.5 ft.  
5/8" Iron rod with plastic cap bears S.34°E., 55.7 ft.  
PK nail in 34" D. fir bears S.67°E., 45.0 ft.  
5/8" Iron rod with plastic cap bears S.67°E., 35.8 ft.  
This point (1/4 cor.) to be destroyed by new road. 1/4 corner located at  
approx. P line station PL 36+30.

3/16/82

See M104-70