

Douglas County Surveyor's Record of
Government Corners Renewed

T 32

T. S.

R 8

R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

111

Section corner for Secs. 28, 29, 32, and 33.
Found - One OBT, 56" sugar pine, N.31°W., 31.7 ft. large face chopped
out 12" deep, previous reported bark scribe destroyed.
Set - 5/8" I. rod at record position, 30" long with yellow cap marked
Thompson PLS 1358".
New BTs - Scribe "T32S R8W S(#) 1358 BT" on the following BTs:
7" tanoak, S.61 1/2°W., 24.8 ft.
7" tanoak, N.48°W., 30.7 ft.
6" madrone, N.52°E., 26.6 ft.
26" S. pine S.28°E., 21.1 ft.
(Note: See narrative in C.S. 58/275 for corroborating evidence)

112

1/4 Corner for Sections 28 and 29.
Set - 5/8" x 30" I. rod with yellow cap marked "Thompson PLS 1358".
New BTs - Scribed the following BTs "1/4S(#) 1358 BT":
9" madrone, S.25 1/2°E., 12.7 ft.
10" D. fir, N.71 1/2°W., 41.2 ft.
Note - Corner is 830 ft. N. of Rd. #32-7-19.3, on N. side of main
ridge, easterly.

113

1/4 Corner for Secs. 28 and 33.
Set - 5/8" x 30" I. Rod with yellow cap mkd. "Thompson PLS 1358"
New BTs - Scribed the following BTs "1/4S(#) 1358 BT":
7" chinquapin, N.53°W., 10.6 ft.
7" cottonwood, S.11°E., 12.5 ft.
Note - Corner is in small draw, S;ly, 95 ft. N. of Rd. #32-8-27, NW'ly
& SE'ly.

114

1/4 Corner for Secs. 32 and 33.
Set - 5/8" I. Rod with yellow cap mkd. "Thompson PLS 1358".
New BTs - Scribed the following BTs "1/4 S 1358 BT":
7" chinquapin, N.65 1/2°W., 15.9 ft.
3" chinquapin, S.44°W., 13.3 ft. with "X BT" scribing.
Note - Corner is on a brushy spur ridge, slopes N'ly.

115

Standard corner for Secs. 32 and 33. (South Tp. line)
Found - 1968 brass cap on 1" G.I. pipe nearly uprooted, lying on surface
of road shoulder. Ren. #82
40" sugar pine, N.8°E., 33.0 ft. face healed.
15" D. fir, S.10°W., 64.1 ft. 1968, face healed.
Set - Since the hole remnant checks with the above BTs, I RESET the
monument therein flush with surface, in NE'ly should of
Rd. No. 34-8-1, NW'ly and SE'ly.

10/21/83

116

Standard Corner for Sections 33 and 34 only.
Found - 11 x 12 x 10 inch stone (1916 Rec. 16x12x7) with 3 grooves on
east & west faces sitting on ground surface with NE corner
of stone checking BT references as shown.
DCSO brass cap out of ground. Ren. #85
Orig. BT, 24" now 32" D. fir with faint evidence of healed blaze
bears N.69°E., 36.5 ft. (Rec. N.68°E., 35.0 ft.)
Orig. BT, 34" now 40" D. fir, faint bark scribe visible S.26°W.,
7.3 ft.
Orig. BT, 16" now 25" D. fir with healed reblaze bears N.42°W.,
13.9 ft. (Rec. N.48°W.).
1968 BT, 9" now 10" madrone with partially healed double blaze
bears N.10°E., 35.7 ft. Ren. #85
Set - The 1968 County brass cap and I.P. (1" x 30") is reset at corner
in mound of stone and earth with 1916 resurvey stone buried
along SW edge. "Reset 1985" is added to cap, top of cap is
flush with mound. NOTE: Top of cap is set at position
determined and referenced for corner. Due to bedrock the mon-
ument cannot be set vertically. Bottom of monument is situated
N.69°E., 0.4 ft. from vertical.

No new accessories added.
(sketch in file)

Robert M. Thompson, LS #1358
For: Boise Cascade Timber Lands of Oregon
October 21, 1983
M 95 - 33
C.S. 58/275 (N)

Larry E. Monr
Deputy, Doug. S.
Surveyors Office
R. W. Smith
S. J. Flause
April 24, 1985
C.S. 62/25