

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

58

$\frac{1}{4}$  Corner to Sections 5 and 8.  
Found - G.L.O. Brass Cap at  $\frac{1}{4}$  Corner Mkd: in 1917.  
18", now 35" D. Fir, S. 23° E. 15.8 ft., shows scar.  
24", D. Fir, now 24" Snag, N. 14° W. 4.7 ft., scribing visible.  
New BT: 6" D. Fir N. 80° E. 56.5 ft. mkd:  $\frac{1}{4}$  S5 CS BT.  
Note - This corner lies 20.0 ft. south of old road in cut unit.

59

$\frac{1}{4}$  Corner to Sections 2 and 1.  
Found - G.L.O. Brass Cap at  $\frac{1}{4}$  corner, properly mkd. in 1917.  
24", now 36" S. Pine, S. 18° E. 76.6 ft., shows good scar.  
No trace of S.W. 9" Laurel BT.  
New BT: 6" Tan Oak S. 49 $\frac{1}{2}$ ° W. 3.4 ft. scribed  $\frac{1}{4}$  S 2 CS BT.

60

Section Corner to Sections 1 - 2 - 11 - 12.  
Found - 26", now 30" D. Fir, N. 86° E. 79.2 ft., shows good scar.  
7", now 28" D. Fir, S. 8° E. 54.1 ft., shows faint scar.  
12", now 19" Laurel S. 4° W. 97.7 ft., opened for scribe "T3".  
No trace of N.W. BT nor Brass Cap as this corner falls in middle of old jeep road.  
Set - Brass Cap for Wit. Corner Mkd: County Surveyor's T32S R9W  
Office W.C. 15' East to  
1967 S 2 | S 1  
S 11 | S 12  
New BT's:  
13" Laurel S. 11 $\frac{1}{2}$ ° W. 12.0 ft. mkd. W.C. T32S R9W S11 CS BT.  
6" Laurel N. 11° W. 10.0 ft. mkd. W.C. S 2 CS BT.  
Rescribed: 28" D. Fir S. 23 $\frac{1}{2}$ ° E. 58.5 ft. mkd. W.C. T32SR9W S12 CS BT.

61

Angle Point on South Boundary of Township.  
This corner lies 62.0 ft. East of  $\frac{1}{4}$  Corner Sec. 36 only which is in good condition. All Trees tagged. Also 140.0 ft. W. of creek 2 lks.  
Found - Orig. 20", now 26" D. Fir, N. 35° W. 27.7 ft., shows good scar.  
Orig. 20", now 22" Laurel, N. 7° E. 31.7 ft., open face & rotted part of "B" legible.  
G.L.O. Brass Cap at A. P. properly marked in 1917.  
Rescribed: 22" Laurel N. 7° E. 31.7 ft. mkd. A. P. CS BT.

62

$\frac{1}{4}$  Corner to Sections 12 and 13.  
Found - G.L.O. Brass Cap at  $\frac{1}{4}$  corner, properly marked in 1917.  
10", now 22" D. Fir, N. 14° W. (Record N. 9° W.) 26.4 ft., shows good scar  
18", now 28" D. Fir, S. 84° W. 70.0 ft., shows good scar.  
Reset Brass Cap as cap was badly bent, we straighten & reset.  
New BT's: 14" D. Fir S. 71° E. 6.8 ft. mkd.  $\frac{1}{4}$  S13 CS BT.  
Rescribed: 22" D. Fir N. 14° W. 26.4 ft. mkd.  $\frac{1}{4}$  S12 CS BT.  
Note - This corner lies approx. 50.0 ft. south of ridge top-running E - W.

63

$\frac{1}{4}$  Corner to Section 18 only, T32-8W.  
Found - G.L.O. Brass Cap properly marked in 1917.  
48" D. Fir, now 52" Stump, N. 71° E. 42.9 ft., opened & shows good scribe.  
16" Sugar Pine, now 27" Stump, S. 69° E. 64.0 ft., shows good scar.  
New BT's: 5" Tan Oak S. 34° W. 9.6 ft. mkd. S18 CS BT.  
48" Sugar Pine N. 30° W. 30.4 ft. scribed  $\frac{1}{4}$  S24 CS BT.  
There were no other trees in Range 8 to scribe.  
Note - This corner lies on the W. of a cutting line.

64

$\frac{1}{4}$  Corner to Section 24 only, T32-9W.  
Found - G.L.O. Brass Cap properly marked in 1917.  
24", now 30" D. Fir, N. 29° W. 13.9 ft., shows good scar.  
6" D. Fir, now out of place due to small slide, (Record S. 60° W. 27.7 ft)  
Almost dead, shows scar.  
New BT: 8" Yew S. 15° W. 10.2 ft. mkd.  $\frac{1}{4}$  S24 CS BT.

John M. Powell  
Frank Jones & J. Brady  
June, 1967  
C. S. File No. 54/44