

Douglas County Surveyor's Record of
Government Corners Renewed

33

T. S.

5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21851

S. W. Corner to Section 31.

(on E & N lines of Sec. 1 T. 33 S. R. 5 W)

Found - Doug. Fir (now 21" diam.) N. 47° E. 21.1 ft. Fragmentary scribing visible on partially rotted face. Did not find marked rock at corner.

Set - Brass Cap Mkd: "County Surveyor's Office 1964

T 32 S " Erect rock mound around pipe.

R S 31 R

5 S 1 4

W W

T 33 S

Rescribe: 21" Doug. Fir N. 47° E. 21.1 ft. Mkd: "T 32 SR 4 W S 31 CS BT"

New BT: 9" Doug. Fir S. 44° E. 11.2 ft. Mkd: "T 33 SR 5 W S 1 CS BT"

Corner lies on very rocky, very steep NW slope.

15

Corner to Sections 1 & 36.

(on W. line Sec. 31 T 32 S.R. 4 W)

Found - Doug. Fir (now 24" diam) S. 60° W. 11.2 ft. Scribing visible on partly exposed face "R 5 W" - tree alive & in good condition.

Doug. Fir (now 23" diam.) N. 62° W. 13.2 ft. Previously opened, but nearly healed over-no scribing visible-tree in good condition.

Doug. Fir (now 26" diam.) N. 42° E. 21.8 ft. (not 17.8 ft) scribing visible on partially exposed face "S31" - tree in good condition.

Partly rotten cedar stump S. 58° E. 25.7 ft. Scribing visible "R 4 W T 33 S S 6"

Set - Brass Cap Mkd: "County Surveyor's Office 1964

T 32 S "

R S 36 SR

5 S 1 4

W W

T 33 S

Did not mark any new trees

Fl. O.K. by:
L. D. SMITH
MAY 14, 1982
M 92-34

16

C. Corner to Sections 1 & 6.

Found - Rock as described, in mound of rocks.

Fir snag N. 46° E. 15.8 ft. Scribing visible "T 33 SR 4 & 5W S 1 & 6 BT"

Fir snag S. 77° E 10.6 ft.-part of face exposed, but no scribing visible.

Doug. Fir (now 15" diam.) S. 39° W. 26.4 ft. Scribing visible on previously opened face. "3S R 5 W S 1"-tree in good condition. A vertical rock cliff approx. 10 ft. high between this tree & corner.

Set - Brass Cap mkd: (on top of bedrock) Mkd: "County Surveyor's Office 1964

T 32 S " Cap not oriented correctly

R S 31 R thus -

5 S 1 64

W W

T 33 S

Erect mound of rocks around pipe.

New BT; 9" Doug. Fir S 65° E 25.0 ft. Mkd: "T 33 SR 4 W S 6 CSBT"

Corner lies on very steep, rocky NW slope.

17

Center 1/4 Section Corner Section 2.

26 links North and 7 links East of Hub.

Set - 1 1/2" Pipe and 6" x 48" Yew Post, from which

BT's: 6" Fir East 1ks. C 1/4 S 2 CS BT.

8" Fir West 35 lks.

COR. SEARCHED FOR, NOT FOUND 8/28/67 June 1930

J.M.P.
C.S. 53/52

18

M. J. Jeffrey, Dep. Surv.
Wm. Stoffel, Mike Darby, Mike Stone
June, 1964
C. S. File No. 53/52

Ben B. Irving
June 1930
C. S. File
No. 37/23
RM 1 - 11