

Douglas County Surveyor's Record of
Government Corners Renewed

T. 33 S. T. S. R. 6 W. R.W.W.M.

ROCKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

New BT's: 11" D. Fir N. 30° E. 16.1 ft. mkd. T33S R6W S9 CS BT.
16" D. Fir S. 3° E. 32.8 ft. mkd. T33 S R6W S16 CS BT.
19" D. Fir S. 23° W. 17.6 ft. mkd. T33S R6W S17 CS BT.
10" Laurel N. 60° W. 15.0 ft. mkd. T33S R6W S8 CS BT.

1/4 Corner to Sections 8 and 17.

FD OK BY G. MYGREN
3/94 M118-79

36

Found - 36" D. Fir, now 48", S. 85° W. 38.3 ft., faint bark scribe "1/4 SBT".
26" D. Fir, now stump, N. 5° E. 39.6 ft., no marks visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 33S R 6 W
Office 1/4 S 8
1967 S 17

New BT: 10" Tan Oak N. 48° W. 26.0 ft. mkd. 1/4 S8 CS BT.
Reblazed & Rescribed: 48" D. Fir S. 85° W. 38.3 ft. mkd. 1/4 S17 CS BT.

1/4 Corner to Sections 8 and 9.

FD OK BY G. MYGREN
3/94 M114-79

37

Found - Orig. 12", now 22" Cedar, S. 43° E. 23.8 ft., shows good scribing
of "1/4 S BT" in the wood.

Orig. 16" Fir, now windfall, N. 32° W. 29.7 ft., no trace of
scribing.

Set - Brass Cap at 1/4 Cor. Mkd: County Surveyor's T33S R 6W
Office, 1967 1/4 S 8 | S 9

Rescribed: 22" Cedar S. 43° E. 23.8 ft. scribed "1/4 S9 CS BT".
New BT: 5" Alder N. 34° E. 7.0 ft. scribed "S8 CS BT". (no other in
range for scribing).

Note - This corner lies 130.0 ft. south of creek and corner lies
in old cutting unit.

Section Corner to Sections 9 - 10 - 15 - 16.

38

Found - 1" Iron Pipe at Section Corner, See Ren. #14.
Orig. 10" D. Fir, now stump, S. 32° E. 12.0 ft., Tree broken off,
found scribe marks.
Orig. 6" D. Fir, now stob, N. 53° W. 22.0 ft., stob flush with ground.
30", now 31" D. Fir, N. 15° E. 21.0 ft., face pitched over.
24", now 24" D. Fir, west 12.0 ft. (Record S. 86° W. 12.0 ft.)
No scribe visible.

New BT's: 25" D. Fir S. 25° E. 8.6 ft. mkd. T33S R6W S15 CS BT.
15" D. Fir N. 57° W. 36.5 ft. mkd. T33S R6W S9 CS BT.
Reblzd. & Rescrbd: 34" D. Fir West 12.0 ft. mkd. T33S R6W S16 CS BT.

Section Corner to Sections 2 - 3 - 10 - 11.

39

Found - Orig. 3", now 11" B. Oak N. 40° E. 7.3 ft., opened for
scribe marks, found but not legible (definite scribe).
Orig. 6", now 17" B. Oak, N. 75° W. 66.0 ft., rotted out.
Old stake at corner very rotten, No trace of other trees.

Set - Brass Cap at Sec. Cor. Mkd: County Surveyor's T33S R6W
Office S 3 | S 2
1967 S 10 | S 11

New BT's: 12" B. Oak S. 23° E. 9.5 ft. mkd. T33S R6W S11 CS BT.
9" W. Oak N. 81° W. 23.7 ft. mkd. T33S R6W S3 CS BT.
4" D. Fir S. 42° W. 8.9 ft. mkd. S10 CS BT.
13" Pine N. 63° E. 13.1 ft. mkd. T33S R6W S2 CS BT.

FD OK M121-31 11/23/94

1/4 Corner to Sections 3 and 2.

40

Found - Unrecorded 1/2" Iron Rod at 1/4 corner & found to be at correct
bearing and distance.

5", now 9" D. Fir, S. 64° E. 34.6 ft., shows scribing "1/4 S2 BT".
16", now 30" D. Fir, N. 46° W. 18.5 ft., shows scribing of "S".

New BT; 26" D. Fir S. 10° E. 14.7 ft. mkd. 1/4 S 2 CS BT.
Note - This corner lies in the S.W. corner of old cutting unit.

FD OK 11/23/94 M121-31

MICROFILM TO HERE 10/67

John M. Powell
Frank Jones & Joe Brady
October, 1967
C. S. File No. 54/53

FD. 7/7/88
J. Hollingsworth
M 107-16 +
C.S. 63/62
Fd 6/90
M110-30

FD. OK 7/13/88
J. Hollingsworth
M 107-16 + C.S.
63/62
Fd 6/90
M110-30