

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 33 S T. S. R 6 W R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

CONT. - - - -

(1/4 Cor. S. 4 only, North) 53
 The computed position for N 1/4 S 4 bears East, 70.0 ft.
 New Accessories:
 29" Ash previously scribed by Epstein and Wenderoth, bears
 S.21 3/4°E., 29.9 ft.
 S 1/4 Cor. S33, T32S R6W (DCSO/BC/IP bears West, 149.2 ft.
 S. Wit. Cor. (1" I.P. Ren. No. 17) bears S.42 1/2° E., 103.8 ft.
 (Sketch of area on notes in file. See DCSO monument recovery quad books
 for coordinate information.)

Doug. Co. Surveyors
 Office - Randall Smith
 S. J. Flause
 M 23,1986
 C 62/34

FOOK BY G. NYGREN
 3/73 4118-79

Center 1/4 Corner Section 5. 54
 Set a 5/8" x 30" Iron rod with plastic yellow cap marked "Hull RS 901".
 New BT'S - 7" Fir bears S88°E, 14.1 ft.
 7" Fir bears N48°E, 19.8 ft.
 12" Fir bears N62°W, 19.0 ft.
 9" Maple bears S61°W, 25.0 ft.

Max Hull
 M 103-35
 C.S. 63/24
 Dec. 1986

W.C. to 1/4 Corner for Sec. 4 only. (north) 55
 Found - A 1" I.D. x 32" long iron pipe with a 1986 DCSO brass cap, bent
 and laying horizontal on top of ground, out of position, set as
 west witness corner per Ren. #53. BC/IP pulled out of ground by
 recent cat work)
 A 1" I.P. flush with ground set by Wenderoth as south witness
 corner per Ren. #17.

Douglas County
 Surveyors Office
 Randall W. Smith
 Stephen J. Flause
 Deputies
 April 6, 1988
 C. S. 62/52

BTs and BOs to west witness corner:
 14" now 29" dia. Ash with a double rotted out blaze facing 1/4
 position as per Ren. #3, tree also is southwest BT to west wit.
 cor., wrongly identified as a maple, with a double partially healed
 blaze, scribing visible facing position of Wenderoth west wit.
 corner, per Ren. #17. Bearing tree bears S.21 3/4° E., 29.9 ft.
 from position of west wit. cor. as established in Ren. #53.
 South 1/4 Cor. for S.33 T.32S R6W (DCSO BC/IP) bears West, 149.2 ft
 5/8" iron rod (east wit. cor. to S 1/4 Cor. S33 T.32S R6W) wrongly
 noted on sketch for Ren. #53 as a 1" I.P., bears west 109.2 ft.
 South wit. cor., A 1" I.P. set flush with ground per Ren. #17 bears
 S.42 1/2°E., 103.8 ft.
 BTs to south witness corner per Ren. #17 are alive and in good
 shape. See Ren. #53
 Set - West wit. cor. established in Ren. #53 is reestablished from found
 accessories per Ren. #53. DCSO BC/IP per Ren. #53 is straightened
 and reset. DCSO BC/IP protrudes 6" above ground and is sur-
 rounded by a 18" dia. 6" high mound of stone. A white steel
 guard post is set 1 ft. east of west wit. corner. "RESET 1988"
 is added to brass cap.

New Accessory:
 1" I.D. iron pipe (4" below ground with a 3/4" I.D. protruding 14"
 and bent to ground, 3/4" iron pipe along north edge of 1" iron
 pipe) bears West 40.2 ft. (source unknown). 4/6/88

North 1/4 Corner for Section 2 only 56
 Found - No original evidence found.
 1" iron rod set by Brandt in 1973 and references as per Ren. #46.
 I do not agree with the method of proportioning used to set this
 corner and I therefore set a new monument for the corner.
 Set - 1" x 30" iron post with a 2 3/8" brass cap mkd. "Oregon State
 Parks T32S R6W 1/4 S2 T33S R6W 1988 LS 691" at proportioned
 distance between the North standard 1/4 corner Sec. 4 and the
 standard corner sections 35 and 36 on a latitudinal curve.

John Hollingsworth
 For: Oreg. State
 Parks & Recreation
 Aug. 23, 1988
 C.S. 63/62
 M 107 - 16

New measurements to existing bearing trees:
 A 16" fir bears S.47°E., 28.9 ft. with healed blaze.
 A 15" fir bears S.23°W., 16.6 ft. with healed blaze.
 A 1" iron rod bears N.37°40'E., 2.6 ft.
 Set orange carsonite post with decal marked "PROPERTY BOUNDARY
 STATE PARK LAND BEHIND THIS SIGN", 2 ft. southeast.

FOOK 11/23/94 M 121-31 8/23/88