

Douglas County Surveyor's Record of  
Government Corners Renewed

33 T. S. 7W R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 97196

Corner of secs. 3, 4, 9, and 10, T. 33 S., R. 7 W., W. M.,  
Determined at the record bearing and distance from the only extant  
original bearing tree.

Set an iron pipe, 3 ft. long, 2 ins. diam., 28 ins. in the ground, mkd.  
RS33;

From which the only extant original bearing tree:

A Douglas fir, 26 ins. diam., bears N. 80°W., 10 lks. dist., mks.  
T33S R7W S4 with BT blaze healed.

And new bearing trees:

A madrona, 7 ins. diam., bears S. 88°E., 44 lks. dist., mkd. T33S  
R7W S10 RS33 BT.

A live oak, 7 ins. diam., bears S. 26°W., 27 lks. dist., mkd. T33S  
R7W S9 RS33 BT.

A madrona, 8 ins. diam., bears N. 47°E., 64 lks. dist., mkd. T33S  
R7W S3 RS33 BT.

1/4 sec. corner of secs. 3 and 4 at proportionate distance.

There is no remaining evidence of the original 1/4 sec. corner.

Set an iron pipe, 3 ft. long, 1 1/2 ins. diam., 28 ins. in the ground,  
mkd. RS33;

From which:

A Douglas fir, 20 ins. diam., bears S. 64°E., 10 lks. dist., mkd.  
1/4 S3 RS33 BT.

A Douglas fir, 15 ins. diam., bears N. 89°W., 9 lks. dist., mkd.  
1/4 S4 RS33 BT. *2-29-68 - FOUND CORNER O.K. J.M.P.*

1/4 sec. corner of secs. 4 and 9.

Determined at the record bearing and distance from the original SE.  
bearing tree.

Set an iron pipe, 3 ft. long, 1 1/2 ins. diam., 28 ins. in the ground,  
mkd. RS33;

From which the only extant original bearing tree:

An incense cedar, 8 ins. diam., bears S. 4°E., 29 lks. dist., mkd.  
1/4 S9 BT.

And a new bearing tree:

An incense cedar, 14 ins. diam., bears N. 74 1/4°E., 46 lks. dist.,  
mkd. 1/4 S4 RS33 BT.

1/4 sec. corner of secs. 4 and 5.

Determined at the record bearing and distance from the original NW  
bearing tree.

Set an iron pipe, 3 ft. long, 1 1/2 ins. diam., 28 ins. in the ground,  
mkd. RS33;

From which the original bearing trees:

A madrona, 13 ins. diam., bears N. 46°W., 22 lks. dist., mkd. 1/4 S5 BT.

A madrona, 12 ins. diam., dead and down and moved out of position  
in a skid road, bears N. 46°E., 46 lks. dist., mkd. 1/4 S4 BT.

*6-4-68 - SEARCHED FOR, NOT FOUND - C.S. 54/36 J.M.P.*

Center 1/4 sec. corner of sec. 4 at intersection with the E. and W.  
center line.

Set an iron pipe, 3 ft. long, 1 1/2 ins. diam., 28 ins. in the ground  
mkd. RS33;

From which:

A yellow pine, 6 ins. diam., bears N. 22 1/4°E., 46 lks. dist., mkd.  
C 1/4 S4 RS33 BT.

A madrona, 6 ins. diam., bears S. 66 1/2°W., 26 lks. dist., mkd. on  
bark C 1/4 S4 RS33 BT.

Section Corner common to Secs. 1 & 6. (Twp. Corner. of T33S Rs. 6 & 7 W.  
Found - Orig. BT. a 12" Ash S. 70°W. 35 lks. with obliterated face.

Other trees gone. Corner falls in Cow Creek.

Set 1 inch iron pipe 35.5 ft. South of True Corner as Witness Corner  
marked with aluminum tag stamped "RE3024", from which pipe the  
following trees bear:

18" Fir bears N. 36°W., 23.5 ft. mkd. "S1WCRE3024BT"

24" Fir bears S. 67 1/4°E., 57.5 ft. mkd. "S6WCRE3024BT"

Norman D. Price, Registered Professional Land Surveyor. Work done on survey for Dollar and Patterson Lumber Co.,  
Glendale, Oregon.  
Survey done between the dates of March 30, to August 18, 1954.  
See County Surveyor's File No. 41/301.

Richard Templin, Jr.  
For Superior Lumber  
Co. of Glendale  
March 11, 1958  
C. S. File No. 42/344