

The South $\frac{1}{2}$ corner of Sec. 20 T. 30 S. R. 5 W. W.M.

I set a 4" squared Oak stake marked $\frac{1}{4}$ from the original tree as described. The tree to the Northeast is standing but dead and the tree to the Southwest is down and rotten. See above writing.

I remarked two new trees

Fir 16" Bears S 58° 20' E 17.3 ft

Fir 8" " S 22° 30' W 37.6 ft

George C. Baker

No 77

Registered Land Surveyor