

April 5, 1949

T 30S RAW

The $\frac{1}{4}$ sec. cor. 29/30 as determined from the remains of the original bearing trees:

A burnt stump, bears N 85 W 31 lks.
A stump hole " S 13 E 28 lks

At cor. set 4" Alder post. from which

An. Alder, 8" diam. bears N 28 E 52'
bark scribed $\frac{1}{4}$ S 2880 B.T.

A Fir, 16" dia. bears N 3 E, 141'
marked $\frac{1}{4}$ S 2880 B.T.

This cor. is 221' South of Beals Cr. there are 3 old fences running North, East + West from this cor.; the post being 12' South of fence COR.

T 30S RAW

The $\frac{1}{4}$ sec. cor. 28/29 as determined from the remains of the original cor.

A burnt stump bears N 85 E 16 lks.
A fir tree bears S 84 W 53 lks. This bearing tree is in good condition

At cor. set 3" fir post, from which

A Fir, 18" dia. bears S 10 W, 38' bark scribed $\frac{1}{4}$ S 2880 B.T.

This $\frac{1}{4}$ cor. is 763' South of the Beals Cr road. The sec. line is fenced North. The center line is fenced East + West from this cor.



Rev. 49
476

CS. 40/179