

Field notes of survey in Section 10, T. 29 S., R.  
20 W. W. M., Douglas County, Oregon.  
Surveyed by J. N. Gearhart, Oregon No. 183.  
Compassman M. S. Hubbard, Oregon No. 1743.  
Chainman Jack Densler.

At the  $\frac{1}{4}$  corner between Sections 9 and 10, T. 29 S., R.  
20 W. W. M., I find the cedar bearing tree N.  $50^{\circ} 00'$  E.  
14 lks to be a snag. No sign of the hemlock bearing tree  
S.  $83^{\circ} 00'$  E. 15 lks.

I mark a red cedar 30 inches in diameter  $\frac{1}{4}$  S 10 B T 1743  
bearing S.  $16^{\circ} 00'$  E. distant 15.5 ft.

---

At the  $\frac{1}{4}$  corner between Sections 10 and 15, T. 29 S.,  
R. 9 W. W. M., I find both bearing trees to be dead snags.

I mark a hemlock 9 inches in diameter  $\frac{1}{4}$  S 15 B T 1743  
bearing S.  $04^{\circ} 00'$  W. distant 20.2 ft.

Measurements to axillary center of tree at top of root  
crown.

J. N. Gearhart  
Oregon No. 183.

Filed June 19, 1950

FILE 253 DENVER 40