

CLAUDE KERR

Real Estate

Timber and Timberlands

ROSEBURG, OREGON

~~MELROSE ROUTE BOX 88-M~~

PHONE 76-J-3

2430 FOOTHILL DRIVE

TIMBER CRUISING
AND
LOGGING ENGINEERING

REGISTERED
PROFESSIONAL
ENGINEER

FILED
RECEIVED

AUG 2 1951

COUNTY SURVEYOR
DOUGLAS COUNTY, OREGON

July 31, 1951

County Surveyor
Courthouse
Roseburg, Oregon

Dear Sir:

I recently found the following corners in T31S, R8W. The corner for 14, 15, 22, & 23.

Found Rock for the corner

The Fir, bearing N 25° E for 10 Lks. is in good condition.

The Fir, bearing S 60° E for 9 Lks. is now snag.

The Fir, bearing S 7° W for 21 Lks. is gone.

The Fir, bearing N 25° W for 57 Lks. is in good condition.

My cruiser mark "K" was left on a BT to make it easier to find.

1/4 Corner for Sections 14 & 23.

Both BTs found and are still live trees.

The 10" Pine (now 22")

The 22" Pine (now 34")

Set 3"x3" Fir Stake, marked 1/4 S 23, 1/4 S 14, T 31S, R8W.

1/4 Corner for Sections 14 & 15.

Found both Bts and the stone.

The 24" Fir bearing S 75° E for 18 Lks. is now 34" in diameter.

The 10" Live Oak bearing N 60° W for 14 Lks. is now 12" in diameter.

Yours truly,

Claude Kerr

recovered only

recovered only

File No. 40/344-2