

March 23, 1955

Mr. Ben Irving  
County Surveyor  
Court House  
Roseburg, Ore.

Bear Mr. Irving:

Enclosed here with is Map and Field notes for your files.

Sincerely Yours  
Kenneth P. McReynolds  
Consulting Forester  
Oregon #277

*by Della C. McReynolds*

FILED  
RECEIVED

MAR 24 1955

COUNTY SURVEY  
DOUGLAS COUNTY, O.

C. S. File No. 41/340

SURVEY NOTES  
of  
C.L.Spaulding Property.

Sections 8 & 9, T22S, R4W, W. M.

Feb. 23, 1955

BEGINNING at the south corner common to Sections 8 & 9, drove an iron rod 5/8" X 30", only one B. T. remained a Cedar stub, I established 3 additional B. T. as follows:

- A Cedar 8" in Dia. which bears North 58° West, 32.8 feet dist.
- A Maple 22" in Dia. which bears North 57° 30' East, 71.0 feet dist,
- A Maple 24" in Dia. which bears South 72° 20' East, 72.0 feet, dist.

Thence north on a declination of 20° 10' a distance of 2640.41 feet and found 1/4 corner, consisting of a 1/2" bolt, previously set, 1 Fir B.T. 60" in Dia. remaining, but all scribe had been burned out, however this tree is North 10° West, Not North 10° East ( correction in notes ) as discribed in notes. Bert Cutlack was present and he was also present almost exactly 50 years ago when the re-survey was made and has lived in the immediate vicinity ever since. He stated that this Fir had always been considered the B.T. I scribed

A Madrone 14" in Dia. which bears North 61° 30' East, 87.0 ft. dist. Then I continued on north and at 2647.18 feet, found North Sec. Cor. common to 8 & 9. B.T. OK. Stake badly rotted, Set Iron Rod 5/8" X 26" in its place. Return turned on line and at 1323.59 feet, Set Iron Pipe 3/4" X 28" from which

A  
Continued back on line and at 1320.21 feet south of 1/4 corner, set South 1/16 corner, consisting of an Iron Pipe 1/2" X 26" from which

A Fir 36" in Dia. bears South 40° East, 9.5 feet dist.

Ran South from the North 1/4 corner of Sec. 9 (recently re-set ) to the South 1/4 corner of said Section, which was found at 5290.48 feet, returned along line and at 1323.41 feet, set South 1/16 corner on center line consisting of an Iron Pipe 1/2" X 30" from which

A Fir 10" in Dia. bears North 80° West, 7.0 feet dist.

This corner is 2689.63 feet East of the South 1/16 corner on Section line between Sections 8 and 9. At 1322.41 feet south of the North 1/4 corner of Sec. 9, set corrected corner, consisting of an Iron Pipe 1/2" X 32" from which

A Fir 32" in Dia. bears South 52° East, 18.0 feet dist.

This corner is 2701.82 feet East of the North 1/16 corner between Sections 8 & 9. The distance between the S.W. corner of Section 8 and the South 1/4 corner of Section 9 was found to be 2683.0 feet and the distance between the N.W. corner of Section 8 and the North 1/4 corner was 2708.0 feet, from the 1/4 corner between Sections 8 & 9 I ran West 1282.0 feet and North 8.0 feet of Gilbert Gardner's Survey. Set approximate 1/16 corner on the center line of the East 1/2 of Section 8.

FILED  
RECEIVED

MAR 24 1955

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 41340

All corners set were an average of the North and South & East and West lines and distances, correction stakes for true line were set as offsets from original lines.

The legal discription of the property surveyed is: the South 1/2 of the N.W. 1/4 of Section 9: the North 1/2 of the S.W. 1/4 of Section 9: the East 1/2 of the S. W. 1/4 of Section 8. all in Township 22 South, Range 4 West of the Willamette Meridian. Douglas County, State of Oregon.

The Survey was made during the months of Dec. 1954 and Feb. 1955. I was assist- ed by C. L. Spaulding, owner, Bert Cutlack, John Jackson and Ted Russell.

See Map for details.

*Kenneth P. Reynolds*  
One 277

FILED  
RECEIVED

MAR 24 1955

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 41340