

FILED
RECEIVED

MAR 24 1955

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

E $\frac{1}{4}$ Cor Sec. 24, T.29S, R.9W.

From O.B.T. in Sec 19, T29S R8W Set this cor ^{and} drove
a $\frac{1}{2}$ " x 20 iron pipe ~~for same~~, from which a $\frac{1}{2}$ " x 23" Iron
Pipe in fence line bears S $89^{\circ}38'$ W 20.0 ft ^{and} a $1\frac{1}{2}$ " x 19"
Iron pipe in fence line bears N $89^{\circ}38'$ E 18.7 ft. —
Corner is in County Road. - (Orig B.T. in sec 19, still standing)

Feb. 7, 1955

Wits. Bernara Denn
W E Howard
Leo Denn

ABoyler

SE Cor. Sec 24 - T29S, R9W.

Found Rock with cross on top 18" below ground surface
on the east shoulder of county road, set a $\frac{1}{2}$ " iron
pipe 18" long on top of this cross, on rock, which is ~~at~~
13 ft W. of the east side of road as fenced and it is
247.5 ft S. of a $\frac{1}{2}$ " x 30" iron pipe which is driven in
the fence on the east side of road: this $\frac{1}{2}$ " x 30" pipe
is in line with a fence that runs west from the road

Feb 8, 1955

Witnesses -- same as above

ABoyler

W $\frac{1}{4}$ Corner Sec 24

Searched diligently for witness trees without success
So set this corner midway between the S.W. ^{and} the N.W.
corners of this section 24 - ^{and} drove a $\frac{3}{4}$ " x 36" iron pipe
at the corner. - Found $\frac{1}{2}$ " i.p. at SW Cor & Wit. Trees at NW Cor
No trees nearby...

Feb 15-1955

witnesses. same as above

ABoyler

C. S. File No. 41/353 A

N $\frac{1}{4}$ Cor Sec 24, T29S R9W Wm. MAR 24 1955

COUNTY SURVEYOR
DOUGLAS COUNTY, IOWA

The timber in the vicinity of a 500 ft. where this corner should be, has been logged off so that there was nothing to indicate ~~any~~ sign of the witness trees: the distance between the NW $\frac{1}{4}$ and the NE corners is 528.28. The N $\frac{1}{4}$ Cor. was set midway between these corners: a $\frac{3}{4}$ " x 48" iron pipe was driven for the corner from which a 9" W.O. tree bears S $80\frac{1}{2}^{\circ}$ E. 32.6 ft., marked $\frac{1}{4}$ S 24 1581 BT. and a 34" fir stump bears N $10\frac{1}{2}^{\circ}$ E 29.1 ft; marked it $\frac{1}{4}$ S. 13, 1581 BT.

Feb 14
1955

witnesses: same as above.

Center Sec 24 -

Feb
17
1955

A $1\frac{1}{4}$ " x 50" iron pipe ^{was} driven at cen. sec. at intersection of N + S and E + W mid sec lines - there are no trees nor distinguishing points for witness points
witnesses as above.

$\frac{1}{16}$ Corners

on N. side NE $\frac{1}{4}$ Sec 24 - drove $\frac{3}{4}$ " x 36" iron pipe there is a yew fence post 4.6 ft E. of corner

Feb
18
1955

on E. side NE $\frac{1}{4}$ Sec 24 drove $\frac{1}{2}$ " x 14" iron pipe in road from which a geared auto axle bears W. 23.5 ft; in fence and a 1" x 24" iron pipe bears E. 18.5 ft. in fence

on S. side NE $\frac{1}{4}$ Sec 24 drove $\frac{1}{2}$ " x 36" iron pipe S. S. File No. 41/353 A

16 corners continued Sec 24 - 29/9

Feb 18 On E. Side SE 4 Sec 24 - Drive $\frac{1}{2}$ " x 15" pipe
for corner ^{in road} from which $1\frac{1}{8}$ " steel bar bears W. 27.3 ft.
and a $1\frac{1}{4}$ " iron pipe 24" lg bears E. 11.9 ft; in fence

Feb 18-55 S. Side SW 4 Sec 24: Drive $\frac{3}{4}$ " I.P. which falls
in fence line

Feb 17-1955 N. Side SW 4 Sec 24 drove $\frac{3}{4}$ " I.P. *A. Boyle*

(All witnesses as above)

FILED
RECEIVED

MAR 24 1955

COUNTY SURVEYOR
DEWEEB COUNTY, ORE.

Boyle