

Re-establishment of 1/4 Corner common
to Sections 3 and 4, Twp. 23 S., R 7 W.

Done August 17, 1954 for Snellstrom Lumber Co. and George E. Winterbotham for establishment of property corner.

I started from the corner of Sections 3 and 4 on Township line which is a 1" iron pipe, and is witnessed by:

- | | | | | | | |
|----|-----|--------|----------------|---------|----------|---------|
| 1. | 30" | D. Fir | (Mk 1/4 S B T) | S 29° W | 17.5 ft. | (Orig.) |
| 2. | 20" | D. Fir | (Mk 2880 B T) | S 26° E | 55.0 ft. | (New) |

Thence: I ran South 5218.65' and arrived 9.2' East of Section corner $\frac{43}{910}$ which is a steel axle and is witnessed by:

- | | | | | | | |
|----|-----|--------------|--|-------------|----------|---------|
| 1. | 24" | D. Fir Stump | | N 15° 30' E | 39.3 ft. | |
| 2. | 10" | D. Fir Stump | | S 69° E | 7.6 ft. | |
| 3. | 18" | Cedar Snag | | N 34° W | 42.4 ft. | |
| 4. | 30" | D. Fir Stump | | S 50° 20' W | 9.6 ft. | |
| 5. | 30" | W. Oak | | S 7° 15" E | 48.9 ft. | (Orig.) |

After diligent search I did not find any trace of original 1/4 corner. Therefore I re-established 1/4 corner by single proportional measurement at a course of S 00° 06' East and distance of 2614.5 ft. from corner of Sections 3 and 4 on North Township line.

The corner is a 1-1/2" x 3' iron pipe and is witnessed by:

- | | | | | | |
|----|-----------------|--------|-----------------------|-------------|----------|
| 1. | 32" | D. Fir | (MK 1/4 S 3 BT LS 307 | S 27° 40' E | 83.2 ft. |
| 2. | 56" | D. Fir | (Mk 1/4 S 54 BT | S 33° 35' W | 68.0 ft. |
| 3. | A fence corner: | | | N 28° 25' E | 40.0 ft. |

Witnesses: Bill Edwards
George F. Winterbotham
Gurley Transit #473458
Var. N 20° E

Scale 1" = 1000'

